



FIR

Product Code	Anil	Centralised ID	DTIL25030040
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	27-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030040
2	Date of complaint	10-10-2000
3	Complaint Raised By	--
4	Complaint Raised Name	Rajesh mtoros -Ramchandrapura Jaipur
5	Contact Number	9390540794
6	Complaint Raised Through	--
7	Service Engineer Name	--
8	Device Model	Anil
9	Device PSN	2408057125
10	VIN Number	MB1H3LHD9RRGZ4937
11	Firmware	G130M153
12	Configuration	--
13	Device IMEI	N/A
14	Device ICCID	8.991643124482294e+19
15	Date of Sale of Device	N/A
16	Telco Status	--
17	Active Profile	--
18	S Trigger Date	N/A
19	C Trigger Date	N/A
20	Commercial Expiry Date	N/A
21	First communication in Darby	N/A
22	Last communication in Darby	N/A
23	Vehicle support Date	N/A
24	Vehicle sale Date	N/A
25	Vehicle Running Location	BHAKROTA-JAIPUR
26	Kilometers/Hours	Kilometers
27	Vehicle Run	8249
28	Main Battery Voltage	24.0
29	Issue Identified	Not Powering ON
30	Issue Analysis	--

31	External Modification		
32	Issue Description	Got vehicle support and found device having m153 sw with pow	
33	Engineer Recommendation	Repair	
34	Device sent to	Goa	
35	Dealer Location	KADAPA■ VEDURURU	
36	Manager Remarks		
37	HOD Remarks		
Approved By:		Name	Signature
Initiated by- Service Eng.		--	--
Service Manager		Kunal	upendram
Sales & Service Head		Rajendran Subramanian	2025-03-27 00:02:14 