



FIR

Product Code	Anil	Centralised ID	DTIL25030041
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	27-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030041
2	Date of complaint	01-01-2000
3	Complaint Raised By	others
4	Complaint Raised Name	
5	Contact Number	9390540794
6	Complaint Raised Through	--
7	Service Engineer Name	--
8	Device Model	Anil
9	Device PSN	1234567878
10	VIN Number	234567890876T5432345
11	Firmware	N/A
12	Configuration	--
13	Device IMEI	N/A
14	Device ICCID	
15	Date of Sale of Device	N/A
16	Telco Status	--
17	Active Profile	--
18	S Trigger Date	N/A
19	C Trigger Date	N/A
20	Commercial Expiry Date	N/A
21	First communication in Darby	N/A
22	Last communication in Darby	N/A
23	Vehicle support Date	N/A
24	Vehicle sale Date	N/A
25	Vehicle Running Location	N/A
26	Kilometers/Hours	Kilometers
27	Vehicle Run	N/A
28	Main Battery Voltage	N/A
29	Issue Identified	Not Powering ON
30	Issue Analysis	--

31	External Modification			
32	Issue Description			
33	Engineer Recommendation		Repair	
34	Device sent to		Goa	
35	Dealer Location		KADAPA■ VEDURURU	
36	Manager Remarks			
37	HOD Remarks			
Approved By:		Name	Date	Signature
Initiated by- Service Eng.		--	27-03-2025	--
Service Manager		Kunal	2025-03-27 00:14:07	upendram
Sales & Service Head		Rajendran Subramanian	2025-03-27 00:14:23	