

		FIR	
Product Code	DL548	Centralised ID	DTIL25040020
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	03-04-2025

SL No.	Description	Details
1	Service Request Number	DTIL25040020
2	Date of complaint	01-04-2025
3	Complaint Raised By	Dealer
4	Complaint Raised Name	Ramujeene
5	Contact Number	9550505680
6	Complaint Raised Through	Telephone
7	Service Engineer Name	Rishwanth
8	Device Model	DL548
9	Device PSN	2212278216
10	VIN Number	MB1NEVHD9PRKH9552
11	Firmware	G114B11321
12	Configuration	Operational Mode
13	Device IMEI	868210062229279
14	Device ICCID	8.9916420534723e+19
15	Date of Sale of Device	01-04-2023
16	Telco Status	Commercial
17	Active Profile	BSNL
18	S Trigger Date	13-04-2023
19	C Trigger Date	22-05-2023
20	Commercial Expiry Date	20-05-2024
21	First communication in Darby	2023-01-09 06:24:00
22	Last communication in Darby	2023-06-07 03:39:00
23	Vehicle support Date	31-03-2025
24	Vehicle sale Date	01-04-2023
25	Vehicle Running Location	KERALA
26	Kilometers/Hours	Kilometers
27	Vehicle Run	15732
28	Main Battery Voltage	24.0
29	Issue Identified	USB Ports Not detect
30	Issue Analysis	USB Ports Not detect

31	External Modification	Others	
32	Issue Description	USB Ports Not detecting	
33	Engineer Recommendation	Repair	
34	Device sent to	Goa	
35	Dealer Location		
36	Manager Remarks		
37	HOD Remarks		
Approved By:		Name	Signature
Initiated by- Service Eng.		Rishwanth	Rishwanth
Service Manager		Narendra	Narendra
Sales & Service Head		Rajendran Subramanian	