

9.4	Integral electrical machines (integrated electrical machine and drive modules)	51
10	Additional considerations for permanent magnet (PM) synchronous electrical machines fed by voltage source converters	51
10.1	System characteristics	51
10.2	Losses and their effects	51
10.3	Noise, vibration and torsional oscillation	52
10.4	Electrical machine insulation electrical stresses	52
10.5	Bearing currents	52
10.6	Particular aspects of permanent magnets	52
11	Additional considerations for cage induction electrical machines fed by high voltage source converters	52
11.1	General	52
11.2	System characteristics	53
11.3	Losses and their effects	54
11.3.1	Additional losses in the stator and rotor winding	54
11.3.2	Measurement of additional losses	54
11.4	Noise, vibration and torsional oscillation	54
11.5	Electrical machine insulation electrical stresses	55
11.5.1	General	55
11.5.2	Electrical machine terminal overvoltage	55
11.5.3	Stator winding voltage stresses in converter applications	55
11.6	Bearing currents	57
12	Additional considerations for synchronous electrical machines fed by voltage source converters	57
12.1	System characteristics	57
12.2	Losses and their effects	57
12.3	Noise, vibration and torsional oscillation	57
12.4	Electrical machine insulation electrical stresses	57
12.5	Bearing currents	57
13	Additional considerations for cage induction electrical machines fed by block-type current source converters	58
13.1	System characteristics (see Figures 30 and 31)	58
13.2	Losses and their effects	59
13.3	Noise, vibration and torsional oscillation	61
13.4	Electrical machine insulation electrical stresses	61
13.5	Bearing currents	61
13.6	Additional considerations for six-phase cage induction electrical machines	61
14	Additional considerations for synchronous electrical machines fed by LCI	62
14.1	System characteristics	62
14.2	Losses and their effects	63
14.3	Noise, vibration and torsional oscillation	63
14.4	Electrical machine insulation electrical stresses	63
14.5	Bearing currents	63
15	Additional considerations for cage induction electrical machines fed by pulsed current source converters (PWM CSI)	64
15.1	System characteristics (see Figure 34)	64
15.2	Losses and their effects	65
15.3	Noise, vibration and torsional oscillation	65

15.4	Electrical machine insulation electrical stresses	65
15.5	Bearing currents	65
16	Wound rotor induction (asynchronous) electrical machines supplied by voltage source converters in the rotor circuit.....	65
16.1	System characteristics	65
16.2	Losses and their effects	65
16.3	Noise, vibration and torsional oscillation	66
16.4	Electrical machine insulation electrical stresses.....	66
16.5	Bearing currents	66
17	Other electrical machine/converter systems.....	66
17.1	Drives supplied by cyclo-converters	66
17.2	Wound rotor induction (asynchronous) electrical machines supplied by current source converters in the rotor circuit	68
18	Special consideration for standard fixed-speed induction electrical machines in the scope of IEC 60034-12 when fed from voltage source converter	68
18.1	Torque derating during converter operation.....	68
18.2	Losses and their effects	70
18.3	Noise, vibrations and torsional oscillation	70
18.4	Electrical machine insulation electrical stresses.....	70
18.5	Bearing currents	71
18.6	Maximum safe operating speed.....	72
19	Additional considerations for synchronous reluctance electrical machine fed by voltage source converters.....	72
19.1	System characteristics	72
19.2	Losses and their effects	72
19.3	Noise, vibration and torsional oscillation	72
19.4	Electrical machine insulation electrical stresses.....	73
19.5	Bearing currents	73
19.6	Particular aspects of synchronous reluctance electrical machines.....	73
Annex A	(informative) Converter characteristics.....	74
A.1	Converter control types	74
A.1.1	General	74
A.1.2	Converter type considerations	75
A.2	Converter output voltage generation (for voltage source converters).....	76
A.2.1	Pulse width modulation (PWM)	76
A.2.2	Hysteresis (sliding mode)	76
A.2.3	Influence of switching frequency.....	76
A.2.4	Multi-level converters.....	78
A.2.5	Parallel converter operation.....	78
Annex B	(informative) Output characteristics of 2 level voltage source converter spectra	79
Annex C	(informative) Voltages to be expected at the power interface between converter and electrical machine.....	83
Figure 1	– Torque/speed capability	15
Figure 2	– Converter output current	16
Figure 3	– Examples of possible converter output voltage/frequency characteristics	18