



Connectors




Relay Circuits










AIR- Weld Detection







Shutdown Sensing






MICROCONTROLLER





Programming LEDs



I removed the flyback diode for the precharge and AIRs' relays. This should go on the new air mounted board.

