

Tablero de Partes

Celda (1, 1) 7114-1170-1 XIC (IC-Traslape) 7114-6042 kic (IC-Traslape) 7114-1982XI C TRY1 MS (IC-Traslape) 7114-2889 pi (IC-Traslape)	Celda (1, 2) 7114-4020-2 XIC (IC-Traslape) 7114-4031-1 XIC (IC-Traslape) 7114-4032 A2XIC (IC-Traslape) 7114-4102-1 XID (IC-Traslape)	Celda (1, 3) 7114-4111-A 1XI (IC-Traslape) 7114-4110 3XI (IC-Traslape) 7114-4112 4XI (IC-Traslape) 7114-4120 A2XI (IC-Traslape)	Celda (1, 4) 7114-4121 1XI (IC-Traslape) 7114-4122-2 XI (IC-Traslape) 7114-4124 2KI (IC-Traslape) 7114-4395 A2XI (IC-Traslape)	Celda (1, 5) 7116-1733-M S XIC (IC-Traslape) 7116-1734 1XIC (IC-Traslape) 7116-1748 1XIC (IC-Traslape) 7116-1735M SXIC (IC-Traslape)	Celda (1, 6) 7116-4024 4XI (IC-Traslape) 7116-4100 1XI (IC-Traslape) 7116-4101 2XI (IC-Traslape) 7116-4113 AXI (IC-Traslape)
Celda (2, 1) 7116-4153-D D A1XI (IC-Traslape) 7116-5452 2KIC (IC-Traslape) 7116-4241 2XIC (IC-Traslape) 7116-4451XI (IC-Traslape)	Celda (2, 2) 7116-4452 A1XIC (IC-Traslape) 7116-4453 3XIC (IC-Traslape) 7116-4872 XI (IC-Traslape) 7116-5361 A1XIC (IC-Traslape)	Celda (2, 3) 7116-5361 XIC (IC-Traslape) 7116-5366 XIC (IC-Traslape) 7116-5625-D IC (IC-Traslape) 7116-4533XI C (IC-Traslape)	Celda (2, 4) 7116-7366XI C (IC-Traslape) 7116-6828 (I C-Traslape) 7116-6828 XI (IC-Traslape) 7116-4533XI C (IC-Traslape)	Celda (2, 5) 7116-2891 XI (IC-Traslape) 7116-6827 1XI (IC-Traslape) 7116-6821 XIC (IC-Traslape) 7116-1986 1XI (IC-Traslape)	Celda (2, 6) 7116-2090 1PIC (IC-Traslape) 7116-3787 2XI (IC-Traslape) 7116-6955 1XIC (IC-Traslape) 7116-5186 XIC (IC-Traslape)
Celda (3, 1) 7116-5308XI C (IC-Traslape) 7116-5309 XIC (IC-Traslape) 7116-4997-A 2XIC (IC-Traslape) 7116-4157-A 1XI (IC-Traslape)	Celda (3, 2) 7116-4513-0 0XIC 7116-1980 1XI (IC-Traslape) 7116-4534-2 XI (IC-Traslape) 7116-7389-1 XIC	Celda (3, 3) 7116-2760 7116-4038-1 APIC 7116-2762 A2XI (IC-Traslape) 7195-1371 1XW (IC-Traslape) 7196-1075 XW (IC-Traslape)	Celda (3, 4) 7196-1283 XIC (IC-Traslape) 7196-2283-0 0XI 7196-2243-0 0XW (WC)	Celda (3, 5) 7196-2972-0 0XW MLX (WC) 7196-0495 XIC 7196-2244-0 0XW (WC) 7196-2250-0 0XIC (IC-Traslape)	Celda (3, 6) 7196-2243-00X I (IC-Traslape) 7196-1286-00X IC 7196-0768-XI- OMLX (IC-Traslape) 7196-2081 00XIC (IC-Traslape)

Celda (4, 1) 7216-7963 XIC TRY (IC-Traslape) 7216-7964 XIC (IC-Traslape) 7216-7965XI C (IC-Traslape) 7216-7657 XIC (IC-Traslape)	Celda (4, 2) 7116-4512-0 0 XIC (IC-Traslape) 7296-1115 KIC TRY (IC-Traslape) 7296-0861-0 0XIC (IC-Traslape) 7296-1244 XIC (IC-Traslape)	Celda (4, 3) 7296-1090-X IC 7296-2511-0 0XW (WC) 7009-6829 MWM (YNCA) (IC-Traslape) 7009-5321-D IC (IC-Traslape)	Celda (4, 4) 7116-1547 XIC (IC-Traslape) 7209-5947 (I C-Traslape) 7116-1473 1XI (IC-Traslape) 7116-3832KI C (IC-Traslape)	Celda (4, 5)	Celda (4, 6)
Celda (5, 1)	Celda (5, 2)	Celda (5, 3)	Celda (5, 4)	Celda (5, 5)	Celda (5, 6)