1. LIS Load



- 사용방법:
 - 1. Interface PC에서 LIS.lis 파일을 생성. (C:₩Seegene_Method_Setting₩LIS₩LIS.lis)

LIS File Format	No	Barcode	Mnemo #1	Mnemo #2		Mnemo #10
	5Byte	20Byte	15Byte	15Byte		15Byte
	total: 175 Byte (one sample)					
	* 1 Byte = 1 Character					

- 2. Launcher에서 Load LIS Data Button클릭 & Yes.
- 3. Worklist확인.