Sensor1 800	Sensor 1 600	Sensor 1 400	Sensor 1 200	Sensor 1 10	0	Sensor2 800	Sensor 2 600	Sensor 2 400	Sensor 2 200	Sensor 2 100	Sensor3 800	Sensor 3 600	Sensor 3 400	Sensor 3 200	Sensor 3 100	Sensor4 800	Sensor 4 600	Sensor 4 400	Sensor 4 200	Sensor 4 100
82	10	3 10	39 26	65	492	87	121	165	258	489	87	98	3 131	1 245	462	8	9 98	3 134	247	474
82	10	3 10	39 26	65	492	87	103	147	261	492	86	98	3 134	4 244	459	14	<mark>0</mark> 94	134	248	474
82	10	3 10	39 26	67	492	87	120	147	258	489	87	98	130	0 244	458	8	9 97	135	5 247	474
82	10	3 10	39 26	66	492	87	103	147	261	487	86	98	143	244	460	8	9 97	134	246	475
82	10	3 10	39 26	66	492	87	121	147	258	488	100	98	130	0 244	457	9	97	134	247	474
107	10	3 10	39 26	67	516	87	103	165	258	488	87	98	131	1 244	459	9	96	135	5 247	525
82	10	3 10	39 26	66	491	87	103	147	258	488	86	99	131	1 243	472	9	97	134	247	474
82	10	3 14	10 29	91	491	105	103	147	257	489	87	99	143	3 245	459	8	98	135	298	472
106	10	3 13	39 26	67	492	87	103	165	262	2 487	87	97	130	0 245	472	8	9 97	134	247	474
82	12	7 10	39 26	36	492	87	121	147	260	488	86	99	130	0 243	459	13	97	134	248	474
82	10	2 14	10 26	36	492	87	103	147	260	489	86	99	134	4 244	460	8	В 93	3 134	248	472
						87	121	146	262	487						14	97	182	25	474