RISK ASSESSMENT

Vessel's Name : JANA 508 Assessment record no. : RA-J508-MOC-01

Date and Time of this assessment : 05TH SEPTEMBER 2026@1500 HRS

Last assessment of similar task : NONE Work activity being assessed : FIRE CONSOLE PANEL REMOVED

State names of Personnel involved in this Risk Assessment and briefing given before commencement of job:

Name & Rank	Signature	Name & Rank	Signature
Master- Denys Cherniavskyi		Chief Engineer - Ruslan Tykhonov	
Chief Officer – Kostyantyn Novichenko			

Task ID	Work process/action undertaken in area	Hazards associated with activity	Controls already in place	Significant risks identified	Further assessment required (Y/N)
01	Fire Alarm Panel removed	Loss of automatic fire detection and alarm monitoring; fire may remain undetected.	Master/OOW informed and removal recorded. Fire Alarm System declared NOT AVAILABLE. Dedicated 24/7 Fire Watch established for the duration of the impairment.	Delayed fire detection / delayed emergency response	**Y**
02	Establish dedicated Fire Watch coverage throughout vessel	Inadequate or incomplete coverage may leave an area without effective fire detection.	Vessel divided into defined Fire Watch areas by deck level and department/defined area. Designated Fire Watch Team Leaders assigned according to vessel layout and available manning. Clear area responsibility and watch handover established.	Fire remaining undetected / delayed fire detection / fire escalation	**Y**
03	Conduct scheduled Fire Watch patrols throughout vessel	Fire may develop between patrols or early indications of fire may be missed.	Minimum hourly rounds maintained throughout vessel, with 30-minute rounds in designated higher-risk areas and increased	Delayed fire detection / delayed emergency response / fire	**Y**

			frequency where conditions warrant. Fire Watch actively checks for smoke, flame, abnormal heat, burning smell, sparks, unusual sounds and other indications of fire.	escalation	
04	Monitor normally unattended and infrequently visited areas	Fire occurring in areas not routinely occupied may remain undetected for an extended period.	Normally unattended and infrequently visited areas specifically identified by OOW/Fire Watch Team Leader and included in patrol plan. Additional rounds conducted. No accessible area excluded from Fire Watch coverage solely because it is not routinely occupied.	Fire remaining undetected / delayed fire detection / fire escalation	**Y**
05	Monitor remote, concealed, enclosed and difficult-access areas	Fire or smoke in concealed, remote or poorly visible locations may remain undetected; unsafe access may delay detection.	Such areas are identified in patrol plans. Checks carried out where safe and practicable. CCTV or other available monitoring used where applicable. Fire Watch shall not enter an unsafe area solely for investigation.	Delayed fire detection / exposure of personnel / fire escalation	**Y**
06	Maintain communication and immediate reporting of fire indications	Detected fire or indication may not be promptly communicated to Bridge/OOW, resulting in delayed emergency response.	Fire Watch personnel and Team Leaders provided with tested portable radio or approved communication means. Any indication of smoke, flame, heat, burning smell, sparks, unusual sounds or other abnormal conditions immediately reported to Bridge/OOW with exact location.	Delayed alarm / delayed emergency response / fire escalation	**Y**
07	Maintain continuous Fire Watch coverage and effective handover	Missed patrol, absence, poor handover or unclear responsibility may leave part of the vessel without effective fire detection.	Team Leaders responsible for assigned deck/department/defined area. Proper handover between watches. Patrol completion monitored. Missed or delayed patrol immediately reported to OOW. No area of vessel left without effective Fire Watch coverage while automatic system is unavailable.	Area left unattended / delayed fire detection / fire escalation	**Y**
08	Restore, test and verify Fire Alarm System before terminating Fire Watch	Fire Watch may be withdrawn while automatic fire detection remains defective or partially operational.	Fire Alarm Panel, detectors, MCPs, audible/visual alarms and relevant indications fully function-tested after reinstallation. Fire Watch maintained until satisfactory	Loss of fire detection / delayed fire detection / fire escalation	**Y**

			restoration confirmed. Withdrawal authorised by Master/OIC.		

Section 1: Hazard Analysis of the Intended Work Activity

Use Risk Matrix poster to complete columns 03, 04 and 05. If the risk Factor is "medium" or above, additional control measures for such risks should be implemented and recorded on section 2 of this form.

Hazard No.	Description of Identified Hazard	Likelihood of harm	Severity of Harm	Risk Factor	Existing or established Control measures to protect personnel.	Document Reference including Permit to Work to be issued
01	Complete loss of automatic fire detection and alarm monitoring due to Fire Alarm Panel removal.	B	II	H	Fire Alarm System declared NOT AVAILABLE and Master/OOW informed. Dedicated 24/7 Fire Watch to be maintained during the impairment. Fire Watch personnel briefed on their duties and assigned areas.	
02	Fire in normally attended areas may remain undetected between Fire Watch rounds.	B	II	H	Regular Fire Watch rounds carried out throughout vessel. Minimum hourly rounds and 30-minute rounds in higher risk areas. Fire Watch to look for smoke, flame, abnormal heat, burning smell, sparks, unusual sounds and other signs of fire.	
03	Fire in normally unattended or infrequently visited areas may remain undetected.	C	II	H	Normally unattended and infrequently visited areas to be identified by OOW/Fire Watch Team Leader and included in patrol plan. Additional rounds to be carried out in these areas. No accessible area to be left without Fire Watch coverage.	
04	Fire in concealed, remote, enclosed or poorly visible locations may remain undetected.	C	II	H	Concealed, remote areas, corners and recesses to be checked during patrols where safe to do so. Particular attention to electrical equipment, machinery spaces, hot surfaces and areas with combustible materials. CCTV or other available monitoring to be used where fitted.	
05	Fire Watch coverage may not be effective due to unclear responsibility, missed rounds, absence or poor handover.	B	II	H	Designated Fire Watch Team Leaders to be assigned for each deck level and department/defined area, as per vessel layout and available manning. Team Leaders responsible for their assigned areas and proper handover. Missed or delayed rounds to	

					be reported to OOW.	
06	Early indication of fire detected but not reported promptly to Bridge/OOW, causing delay in response.	C	II	H	Fire Watch personnel and Team Leaders to maintain communication with Bridge/OOW by portable radio or other approved means. Any smoke, flame, heat, burning smell, sparks, unusual sound or other indication of fire to be reported immediately with exact location.	
07	Fire in restricted, difficult access or temporarily inaccessible areas may remain undetected or detection may be delayed.	C	II	H	Such areas to be identified in the Fire Watch patrol plan. Where direct access is not safe, monitoring to be carried out from safe location or by CCTV/other available means where fitted. Fire Watch personnel do not enter unsafe area only for investigation.	
08	Fire Watch may be stopped before automatic fire detection system is fully restored and verified.	D	II	M	Fire Watch to continue until Fire Alarm Panel, detectors, MCPs, audible/visual alarms and relevant indications are tested and confirmed operational. Fire Watch withdrawal only after confirmation by Master.	

Section 2 : Additional Control measures

Hazard No.	Short Description of Identified Hazard Section	Further Risk Control measures to reduce risk	Responsible Person	Review
1	Loss of automatic fire detection	Declare the Fire Alarm Panel unavailable and establish dedicated Fire Watch coverage for the vessel until the system is restored and verified operational.	Master / OOW	Continuous

2	Incomplete Fire Watch coverage	Divide the vessel into defined Fire Watch areas by deck and department, with a designated Team Leader responsible for each assigned area.	Master / OOW	Before / during
3	Fire not detected between patrols	Carry out scheduled Fire Watch rounds throughout the vessel. Personnel shall actively look for smoke, flame, abnormal heat, burning smell, sparks or other indications of fire.	Fire Watch Team Leaders	Continuous
4	Fire in normally unattended / infrequently visited areas	Identify all normally unattended and infrequently visited spaces and include them in the Fire Watch patrol plan. Additional rounds shall be carried out where required.	OOW / Team Leaders	Continuous
5	Fire in remote / concealed areas	Ensure remote, concealed, enclosed and poorly visible areas are specifically identified and physically checked where safe and practicable. No accessible area shall be excluded from the patrol plan.	Fire Watch Team Leaders	Continuous
6	Fire indication not reported promptly	Provide Fire Watch personnel with a tested means of communication and require any indication of fire, smoke, abnormal heat or burning smell to be reported immediately to the Bridge/OOW with the exact location.	OOW / Fire Watch Team Leaders	Continuous
7	Missed patrol / ineffective handover	Maintain clear area responsibility and proper handover between Fire Watch personnel. Any missed or delayed patrol shall be immediately brought to the attention of the OOW and corrective coverage arranged.	OOW / Team Leaders	Each watch
8	Fire Watch withdrawn before system restoration	Fire Watch shall remain in place until the Fire Alarm Panel and associated detection/alarm functions have been restored, tested and confirmed operational. Withdrawal of additional Fire Watch shall be authorized by the Master/OOW.	Master / OOW	Before closure

During the period in which the Fire Alarm Panel is declared NOT AVAILABLE, the vessel shall maintain continuous and fully documented Fire Watch coverage across all decks, accommodation levels, machinery spaces, remote areas, concealed spaces and normally unattended locations. A Fire Watch Tracker shall be implemented, assigning specific personnel to each defined area with clear patrol frequency (hourly or 30-minute rounds as applicable), mandatory communication checks, and recorded findings for every patrol. No area of the vessel shall remain unmonitored at any time. Any equipment, electrical panel, machinery or system that becomes unsafe to operate without automatic fire detection—or is under repair, isolation, or troubleshooting related to the fire alarm system—shall be isolated and LOTO-tagged until safe operation is confirmed. All LOTO actions shall be logged in the LOTO Tracker and verified by the OOW.

Fire Watch personnel shall immediately report any smoke, flame, abnormal heat, burning smell, sparks, unusual sound or other abnormal condition to the Bridge/OOW with exact location. Missed rounds, delayed patrols or incomplete coverage shall be escalated without delay and corrective coverage arranged. Fire Watch arrangements, area assignments, LOTO status and patrol logs will remain active until the Fire Alarm Panel and all associated alarm functions are fully restored, tested and verified operational by the responsible officer and accepted by the Master.
Assessment Review Date:
Name and Signature:

RISK MATRIX

In cases where the Risk is:

High : Work shall not start unless approval obtained from management ashore.
Moderate : Efforts should be made to reduce the risk, with heightened monitoring of the additional controls implemented.
Low : No additional controls required; monitoring required to ensure controls maintained

	A	B	C	D	E
I	H	H	H	H	M
II	H	H	H	M	M
III	H	H	M	M	L
IV	H	M	M	L	L
V	M	M	L	L	L

Risk Letter	Likelihood of it happening	Estimated frequency of incidents
A	Possibility of repeated events	One or more times per month
B	Possibility of isolated incidents	One or more times per quarter
C	Possibility of occurring sometime	One or more times in 1 year
D	Not likely to occur	Less than once in 5 years
E	Very Remote Probability of occurrence	Less than once in 10 years

Consequence Category	Health and Safety	Damage to Vessel/Property	Environmental Impact	Other Impact
I	Fatality, Serious impact on Public	Total Loss. Immediate layup/dry docking for major repairs. Major claims from 3rd Parties.	Spill/discharge in water > 100L	Major Industry Reaction. Fleet-wide blacklist by one or more Oil Majors.
II	Permanent Disability, Limited impact on Public	Requiring layup repairs, 3rd Party Claims.	Spill/discharge in water < 100L	Extensive Off-hire, Loss of Charter, Blacklisting of vessel by more than one Oil Major.
III	Serious injury or multiple minor injuries requiring Hospitalization (Sign Off) (LTI)	Affecting sea worthiness, repaired with or without shore assistance. Leading to COC to be cleared by next D/D.	Spill on deck > 1m3	Major Off hire, Blacklisting of vessel by one Oil Major.
IV	Injury requiring medical treatment ashore (MTC)	Not affecting sea worthiness, repair requiring external assistance.	Spill on deck < 1m3	Minor Off hire
V	Simple First Aid or NLTI	Not affecting sea worthiness repairable by ship staff.	Accidental discharge within containment tray.	Operational delay