

Broker Notes

Recent roof replacement completed in 2023. Water mitigation details pending.