



689 Sharp edges to be removed.

O.PHJ

Tolerances for dimensions without tolerance indication (ISO 2900-1990)											
This standard states the permissible deviations for dimensions without direct tolerance indications on metallic components manufactured by machining.											
Permissible deviation	Basic size range mm										
	0,5 up to 1	over 1 up to 3	over 3 up to 10	over 10 up to 30	over 30 up to 100	over 100 up to 300	over 300 up to 1000	over 1000 up to 2000	over 2000 up to 3000	over 3000 up to 4000	over 4000 up to 5000
Medium series	±0,1	±0,2	±0,3	±0,5	±0,8	±1,2	±1,6	±2,0	±2,5	±3,0	±4,0