

Inspection IR-T1-2026-07 — rail profile measurement, T1 segment S07

Segment	TRK-T1-S07, chainage 3+420 to 3+980, both tracks
Method	Rail profile measurement (0-100 wear scale)
Date	14 July 2026
Inspector role	Track engineer

Chainage	Vertical wear (mm)	Lateral wear (mm)	Wear index	Finding
3+450	6.1	8.9	78	Significant
3+500 (curve R 32 m)	7.4	12.2	94	Replacement threshold reached
3+620	5.2	6.0	61	Minor
3+900	4.8	5.1	55	Minor

Recommendation: replace both rails through the curve within 6 months. A 30 km/h speed restriction applies from 15 July 2026.

Measurements — every 20 m

Chainage	Rail	Vertical wear (mm)	Lateral wear (mm)	Wear index	Finding
3+420	both	6.8	13.2	83	Significant
3+440	outer rail	6.7	13.0	81	Significant
3+460	both	6.9	13.4	85	Significant
3+480	outer rail	7.2	14.3	93	Replacement threshold reached
3+500	both	7.2	14.3	93	Replacement threshold reached
3+520	outer rail	7.1	13.9	89	Significant
3+540	both	6.9	13.6	86	Significant
3+560	outer rail	6.8	13.1	82	Significant
3+580	both	6.8	13.2	83	Significant
3+600	outer rail	6.5	12.3	75	Significant
3+620	both	6.5	12.4	76	Significant
3+640	outer rail	6.4	12.1	73	Significant
3+660	both	6.3	11.7	69	Minor
3+680	outer rail	5.9	10.8	61	Minor
3+700	both	6.0	10.9	62	Minor
3+720	outer rail	5.8	10.4	58	Minor
3+740	both	5.5	9.7	51	Minor
3+760	outer rail	5.4	9.3	48	Minor
3+780	both	5.3	9.0	45	Minor
3+800	outer rail	5.2	8.7	42	Minor
3+820	both	5.1	8.4	40	Minor
3+840	outer rail	5.1	8.4	40	Minor

Chainage	Rail	Vertical wear (mm)	Lateral wear (mm)	Wear index	Finding
3+860	both	5.1	8.4	40	Minor
3+880	outer rail	5.1	8.4	40	Minor
3+900	both	5.1	8.4	40	Minor
3+920	outer rail	5.1	8.4	40	Minor
3+940	both	5.1	8.4	40	Minor
3+960	outer rail	5.1	8.4	40	Minor
3+980	both	5.1	8.4	40	Minor

Replacement threshold: wear index 90. Measurements by profile trolley, calibration certificate CAL-2026-0311. Scale 0-100; not comparable with the 1-5 condition scale used for substations.