

Condition assessment — traction substation SST-04 Pont Neuf — 2026

Asset	SST-04, 750 V DC, two rectifier groups
Method	Thermography, protection testing, obsolescence review
Score	2 on the 1-5 scale (poor)

Rectifier group 2 is past manufacturer end of support (December 2025). Two trips on 3 February and 22 April 2026 caused T1 service loss of 38 and 51 minutes. Spares are cannibalised from SST-07 stock.

Test	Result	Limit
Rectifier group 1 — thermography	58 °C hot spot	< 70 °C
Rectifier group 2 — thermography	81 °C hot spot	< 70 °C
DC breaker trip time	38 ms	< 50 ms
Earth fault protection	Pass	—
Spares availability (group 2)	None from manufacturer	—

Recommendation: replace rectifier group 2 and the associated protection; keep group 1 under monitoring.