



## High Plains Property Maintenance

14847 Madison St

7208109673

randy@highplainsprop.com

# Irrigation Billing Detail

Monthly service documentation for Woodglenn Squares HOA

Billing Period: May 1, 2026 – May 31, 2026

INVOICE #82883

Prepared for: **Woodglenn Squares HOA**

### INVOICE TOTAL

# \$2,864.91

#### LABOR

**\$1,997.50**

#### PARTS

**\$867.41**

#### JOBS

**7**

**7**

BILLING SHEETS

**0**

WORK ORDERS

**0**

WET CHECK BILLINGS

### WHAT'S INCLUDED

1. **Reconciliation Summary** — line-item breakdown of all charges for this billing period
2. **Billing Sheet Detail** — technician notes, parts, and labor for each service ticket
3. **Work Photos** — site and field photos attached to completed tickets

### HOW TO REVIEW

Start with the **Reconciliation Summary** on the next page for a quick overview of all charges. Then turn to the **Billing Sheet Detail** pages for full technician notes and parts used on each visit. Site photos follow each ticket where available. Contact us with any questions before your payment due date.

# Invoice Reconciliation Summary

Invoice #82883 · May 1, 2026 – May 31, 2026

| REFERENCE #             | TYPE          | TOTAL      |
|-------------------------|---------------|------------|
| BILLING SHEETS          |               |            |
| BS-2026-0167            | Billing Sheet | \$504.45   |
| BS-2026-0156            | Billing Sheet | \$963.40   |
| BS-2026-0155            | Billing Sheet | \$189.80   |
| BS-2026-0152            | Billing Sheet | \$646.00   |
| BS-2026-0117            | Billing Sheet | \$268.68   |
| BS-2026-0114            | Billing Sheet | \$94.61    |
| BS-2026-0110            | Billing Sheet | \$197.97   |
| Billing Sheets Subtotal |               | \$2,864.91 |
| GRAND TOTAL             |               | \$2,864.91 |

|               |            |
|---------------|------------|
| Total Labor   | \$1,997.50 |
| Total Parts   | \$867.41   |
| Invoice Total | \$2,864.91 |



## Billing Sheet #BS-2026-0167 | Invoice #82883

Date: May 26, 2026 | Technician: Bryan Krisher | Hours: 4 hrs

□ C/O Advance HOA Management Denver CO 80237

### WORK PERFORMED

- The mainline was expertly repaired after sustaining damage, likely caused by direct boring.
- Our team ensured that the system was restored to optimal functionality, addressing the issue promptly and efficiently.

### FINANCIAL BREAKDOWN

|                                       |                 |
|---------------------------------------|-----------------|
| Irrigation Labor (4 hrs × \$85.00/hr) | <b>\$340.00</b> |
| Parts Subtotal                        | <b>\$164.45</b> |
| <b>TOTAL</b>                          | <b>\$504.45</b> |

### PARTS & LABOR DETAILS

| PART DESCRIPTION                                                         | QTY  | UNIT PRICE | TOTAL   |
|--------------------------------------------------------------------------|------|------------|---------|
| Rain Bird Swing Elbow (1/2" Barb x Thread - SBE-050 / SWGE050 / SWGF050) | 1.00 | \$2.50     | \$2.50  |
| Duracell 9 Volt Battery                                                  | 2.00 | \$12.00    | \$24.00 |
| Glue & Primer Application (1)<br>Glue & Primer Application (1)           | 4.00 | \$1.80     | \$7.20  |
| Fitting - PVC - 2" - Slip-Fix (Telescoping Repair Coupling)              | 1.00 | \$78.00    | \$78.00 |
| Bushing - PVC - 4" - 2" x 1"<br>SCHEDULE 40 PVC BUSHING 2"x1"            | 1.00 | \$39.90    | \$39.90 |
| 2" Coupling                                                              | 1.00 | \$4.95     | \$4.95  |
| Pipe — PVC — 2" (Schedule 40 baseline)                                   | 1.00 | \$7.90     | \$7.90  |

WORK PHOTOS





## Billing Sheet #BS-2026-0156 | Invoice #82883

Date: May 21, 2026 | Technician: Admiel | Hours: 10 hrs

□ C/O Advance HOA Management Denver CO 80237

### WORK PERFORMED

- A broken main line located beneath the driveway's cement was repaired.
- The damaged section, including the coupling and slip fix, was replaced with a new slip fix, a 90-degree elbow, a coupler, and additional PVC piping to ensure no further leaks.

### FINANCIAL BREAKDOWN

|                                        |                 |
|----------------------------------------|-----------------|
| Irrigation Labor (10 hrs × \$85.00/hr) | <b>\$850.00</b> |
| Parts Subtotal                         | <b>\$113.40</b> |
| <b>TOTAL</b>                           | <b>\$963.40</b> |

### PARTS & LABOR DETAILS

| PART DESCRIPTION                                                           | QTY  | UNIT PRICE | TOTAL   |
|----------------------------------------------------------------------------|------|------------|---------|
| Pipe — PVC — 1.5" (Schedule 40 baseline)                                   | 1.00 | \$7.10     | \$7.10  |
| Fitting - PVC - 1.5" - Slip Coupler<br>Fitting - PVC - 1.5" - Slip Coupler | 1.00 | \$14.00    | \$14.00 |
| Fitting - PVC - 1.5" - 90° Elbow (Slip x Slip)                             | 1.00 | \$15.00    | \$15.00 |
| Fitting - PVC - 1" - Coupler (Slip x Slip)                                 | 1.00 | \$9.50     | \$9.50  |
| Fitting - PVC - 1.5" - Slip-Fix (Telescoping Repair Coupling)              | 1.00 | \$57.00    | \$57.00 |
| Glue & Primer Application (1)<br>Glue & Primer Application (1)             | 6.00 | \$1.80     | \$10.80 |

WORK PHOTOS







**Billing Sheet #BS-2026-0155 | Invoice #82883**

Date: May 21, 2026 | Technician: Admiel | Hours: 1.5 hrs

□ C/O Advance HOA Management Denver CO 80237

**WORK PERFORMED**

- Two sprinkler heads were addressed during the service. One head had detached completely and was reinstalled, while the other was missing its internal components and was repaired accordingly.

**FINANCIAL BREAKDOWN**

Irrigation Labor (1.5 hrs × \$85.00/hr) **\$127.50**

Parts Subtotal **\$62.30**

**TOTAL \$189.80**

**PARTS & LABOR DETAILS**

| PART DESCRIPTION                                    | QTY  | UNIT PRICE | TOTAL   |
|-----------------------------------------------------|------|------------|---------|
| Head - K-Rain 1806 Pop-Up Spray Body                | 2.00 | \$28.75    | \$57.50 |
| Filter - Pop-Up Spray Filter (Nozzle Screen Filter) | 2.00 | \$2.40     | \$4.80  |

**WORK PHOTOS**





## Billing Sheet #BS-2026-0152 | Invoice #82883

Date: May 20, 2026 | Technician: Bryan Krisher | Hours: 2 hrs

□ C/O Advance HOA Management Denver CO 80237

### WORK PERFORMED

- An emergency service was conducted to address a significant leak in the backflow preventer.
- The seal kit was replaced to resolve the issue, and the test cock was also replaced to ensure proper functionality.

### FINANCIAL BREAKDOWN

|                                       |                 |
|---------------------------------------|-----------------|
| Irrigation Labor (2 hrs × \$85.00/hr) | <b>\$170.00</b> |
| Parts Subtotal                        | <b>\$476.00</b> |
| <b>TOTAL</b>                          | <b>\$646.00</b> |

### PARTS & LABOR DETAILS

| PART DESCRIPTION         | QTY  | UNIT PRICE | TOTAL    |
|--------------------------|------|------------|----------|
| 2" FEBCO Seal Kit        | 1.00 | \$430.00   | \$430.00 |
| Backflow Test Cock Valve | 1.00 | \$46.00    | \$46.00  |

### WORK PHOTOS







**Billing Sheet #BS-2026-0117 | Invoice #82883**

Date: May 8, 2026 | Technician: Bryan Krisher | Hours: 3 hrs  
□ C/O Advance HOA Management Denver CO 80237

**WORK PERFORMED**

- The irrigation system controller was successfully rewired following the activation of the meter, with assistance from the Property Manager.
- This ensures optimal functionality and efficient water management for the property.

**FINANCIAL BREAKDOWN**

|                                       |                 |
|---------------------------------------|-----------------|
| Irrigation Labor (3 hrs × \$85.00/hr) | \$255.00        |
| Parts Subtotal                        | \$13.68         |
| <b>TOTAL</b>                          | <b>\$268.68</b> |

**PARTS & LABOR DETAILS**

| PART DESCRIPTION     | QTY  | UNIT PRICE | TOTAL   |
|----------------------|------|------------|---------|
| Wire Nuts Waterproof | 4.00 | \$3.42     | \$13.68 |

**WORK PHOTOS**





**Billing Sheet #BS-2026-0114 | Invoice #82883**

Date: May 7, 2026 | Technician: Bryan Krisher | Hours: 1 hrs

□ C/O Advance HOA Management Denver CO 80237

**WORK PERFORMED**

- Replaced the batteries on the DC operating controller to ensure optimal performance and reliability. This maintenance task helps in maintaining consistent irrigation scheduling and functionality.

**FINANCIAL BREAKDOWN**

|                                       |                |
|---------------------------------------|----------------|
| Irrigation Labor (1 hrs × \$85.00/hr) | \$85.00        |
| Parts Subtotal                        | \$9.61         |
| <b>TOTAL</b>                          | <b>\$94.61</b> |

**PARTS & LABOR DETAILS**

| PART DESCRIPTION       | QTY  | UNIT PRICE | TOTAL  |
|------------------------|------|------------|--------|
| AA batteries energizer | 1.00 | \$9.61     | \$9.61 |

**WORK PHOTOS**





## Billing Sheet #BS-2026-0110 | Invoice #82883

Date: May 5, 2026 | Technician: Bryan Krisher | Hours: 2 hrs

☐ Backflows

### WORK PERFORMED

- Insulated backflow preventer

### FINANCIAL BREAKDOWN

Irrigation Labor (2 hrs × \$85.00/hr) **\$170.00**

Parts Subtotal **\$27.97**

**TOTAL \$197.97**

### PARTS & LABOR DETAILS

| PART DESCRIPTION | QTY  | UNIT PRICE | TOTAL   |
|------------------|------|------------|---------|
| R 13 insulation  | 1.00 | \$27.97    | \$27.97 |

### WORK PHOTOS

*No photos captured for this service*