



Document Effective Date
11/09/2024

**IS PROCEDURE FOR PERSONAL PROTECTIVE
EQUIPMENT SELECTION & USE**

DOC NO: IS-HSE-PRC-005

Rev: 04

Quality Reviewed By: OIB/4

CUSTODIAN DEPARTMENT	DOCUMENT AUTHOR	DOCUMENT OWNER
HEALTH, SAFETY & ENVIRONMENT (IDD EL-SHARGI)		
	OIH/15	OIH/1

FINAL APPROVAL
OIH

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

TABLE OF CONTENTS

Page No.

1.0 PURPOSE	4
2.0 SCOPE AND APPLICABILITY.....	4
3.0 ROLES AND RESPONSIBILITIES.....	4
4.0 PROCEDURAL STEPS.....	5
4.1 GENERAL	5
4.2 HAZARD ASSESSMENT AND PPE SELECTION	6
4.3 TRAINING	6
4.4 HAND PROTECTION.....	7
4.5 QATARENERGY-IS JEWELLERY POLICY	9
4.6 BODY PROTECTION/CLOTHING	9
4.7 EYE AND FACE PROTECTION.....	10
4.8 HEAD PROTECTION.....	11
4.9 FOOT PROTECTION.....	11
4.10 HEARING PROTECTION	12
4.11 SPECIALIST PPE	12
4.12 MACHINE GUARDING	13
4.13 GREEN HARD HAT POLICY	13
4.14 FALL PROTECTION	14
4.15 RESPIRATORY PROTECTION	14
4.16 PROGRAM MONITORING	14
4.17 PPE ON PS-1-Q MAIN DECK	15
4.18 DOCUMENTATION AND RECORDKEEPING.....	15
5.0 REFERENCES TO OTHER DOCUMENTS	16
6.0 DEFINITIONS.....	16
APPENDIX.....	17
APPENDIX A - HAND PROTECTION	17
APPENDIX B - BODY PROTECTION / COVERALLS.....	18
APPENDIX C - SAFETY GLASSES / EYE PROTECTION	21
APPENDIX D - HEAD PROTECTION	24

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	--

APPENDIX E - FOOT PROTECTION 26

APPENDIX F: WINTER JACKET SPECIFICATION 27

APPENDIX G - GREEN HAT EVALUATION QUESTIONNAIRE 29

APPENDIX H: PERSONAL CONTROL DESCENT DEVICE (DONUT)
FAMILIARIZATION..... 31

APPENDIX I – REVISION HISTORY LOG..... 31

APPENDIX J – LIST OF ABBREVIATIONS 32

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

1.0 PURPOSE

To specify minimum requirements for the selection and use of Personal Protective Equipment (PPE) at all QatarEnergy-IS operated locations both onshore and offshore as identified by a hazard assessment. The use of personal protective equipment as specified by this Procedure is designed to supplement effective engineering and administrative hazard controls.

2.0 SCOPE AND APPLICABILITY

This Procedure applies to all employees, contractors and visitors when on QatarEnergy-IS operated locations.

3.0 ROLES AND RESPONSIBILITIES

DEPARTMENT MANAGERS/LEAD

- Ensure this Procedure is communicated within their department or team.
- Ensure training has been provided for the use and maintenance of Personal Protective Equipment, as/when required.
- Approve PPE Hazard Assessments and Selection as appropriate.
- Ensure approved PPE is provided.

SR. SAFETY OFFICER

- Ensure PPE, which has a designated international equivalent Standard, meets the requirements of the Standards where identified in this Procedure.
- Ensure that a training program for the selection and use of Personal Protective Equipment is developed and made available to the QatarEnergy-IS.

SAFETY OFFICER

- Ensure the correct type of PPE is being worn as per risk assessment, SDS (Safety Data sheet).
- Conduct an onsite PPE inspection and report findings in the HSE Tracker.
- Provide PPE advice to the work force during training, safety meetings and toolbox tasks.
- Reviews all 'Green Hat Evaluation Questionnaires' completed by the worksite supervisors for new staff and contractors.

OFFSHORE & ONSHORE SUPERVISORS

- Ensure that permit applicants under their supervision perform workplace hazard assessments and PPE hazard assessments to recognize and identify potential hazards and determine the necessary PPE to reduce the associated risks.
- Maintain all records associated with workplace hazard assessments and PPE hazard assessments.



IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE

DOC NO : IS-HSE-PRC-005

REV. 04

- Responsible for conducting 'Green Hat Evaluation Questionnaires' utilizing Appendix-I for all new staff and contractor personnel under their direct supervision and maintain completed records.
- Ensure that the PPE selected is appropriate for the job.
- Ensure personnel including contractors have been trained in the use of PPE and are familiar with this Procedure.
- Enforce the requirements of this Procedure.

EMPLOYEES & CONTRACTORS

- Understand the need for and correctly wearing of PPE whenever required for a specific task or in designated areas.
- Take reasonable care of their PPE and secure replacement when needed.

4.0 PROCEDURAL STEPS

4.1 GENERAL

QatarEnergy-IS shall develop and implement a documented PPE Program to assess and mitigate hazardous exposure in the workplace and advise the workforce on the appropriate protective equipment to mitigate identified hazards.

Hazard assessments shall be conducted, documented by competent personnel and shared with the workforce.

PPE Program shall be documented and include the following elements:

- Hazard Assessment and PPE Selection.
- Employee Training.
- Documentation and Recordkeeping.
- Regular Periodic Review (5 years, after an incident/ Injury involving PPE).
- Minimum Standards:
- Personal protective equipment (PPE) shall be worn by all employees, contractors and visitors on all QatarEnergy-IS facilities.
- Selection of PPE shall be based on a hazard assessment, work site risk assessment (ISSoW), as identified in a safety data sheet (SDS).
- The design and construction of supplied PPE shall comply with Standards as identified in this Procedure.
- All PPE shall be stored and maintained in a serviceable condition as per manufacturer's instructions.
- Each person shall be responsible for checking their own PPE, before starting any work activity.
- Any signs of wear or damage on the PPE, the user shall report the defect and discarded the item unfit for purpose.
- PPE shall not be modified without the approval from the manufacturer.
- PPE Components from different manufacturers shall not be combined in a protective equipment system unless compatible.
- PPE designated as '**DISPOSABLE**' shall only be used once, disposed of and never re-used.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

- Contractors are responsible for supplying their own Personal Protective Equipment to comply with this Procedure.
- QatarEnergy-IS Contractors working on non QatarEnergy-IS operated locations (e.g. drilling rigs) shall have their own PPE policy that meets or exceeds the requirements of this Procedure.
- QatarEnergy-IS shall reserve the right to replace or substitute PPE, as and when required.
- In areas where specific PPE is required to be worn, signs shall be posted that specify these requirements.

4.2 HAZARD ASSESSMENT AND PPE SELECTION

QatarEnergy-IS personnel, including contractors, shall evaluate the Workplace to determine the types of hazard that are present, or likely to be present to which an employee(s) can be exposed to. This assessment includes personal or job grouping evaluation of tasks performed and the PPE required for each task. PPE Hazard Assessment will take precedence, and is supported by the ISSoW worksite risk assessment.

QatarEnergy-IS Hazard Assessment process shall consider protection from hazards that include but not limited to the employee's:

- Face and Eyes include such hazards as flying particles, liquid, gas or chemical vapors, acids, caustic liquids, light radiation or hydrocarbons.
- Feet.
- Hands.
- Head.
- Hearing (for tasks not identified in the QatarEnergy-IS Hearing Conservation Protection).
- Respiratory (For tasks not identified in QatarEnergy-IS Respiratory Protection Program).
- Fall Protection (for tasks not identified in the QatarEnergy-IS Fall Protection Program).
- Body.

4.3 TRAINING

Employees, Contractors and visitors shall be advised to:

- a) Identify when and where PPE is necessary.
- b) Demonstrate the correct use of PPE (donning, removing and adjusting wearing the PPE).
- c) Properly care, store and when appropriate, dispose of/replace PPE in conformance with applicable workplace laws and regulations and the manufacturer's recommendation and documentation.
- d) Understand assessment results and the selection of PPE for each task they are required to perform.
- e) Understand the limitations of the selected PPE.
- f) Access appropriate resources to help determine the appropriate PPE for a task not covered by the current hazard assessment, Safety Data sheet (SDS), Job Safety Analysis (JSA) training matrix.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

This training shall be provided during training sessions, work site inductions or during work activities (toolbox talks).

4.4 HAND PROTECTION

QatarEnergy-IS including contractors shall select and require employees to use appropriate hand protection when hands are exposed to hazards such as:

- Severe cuts or lacerations.
- Severe abrasions.
- Punctures.
- Skin absorption of harmful substance.
- Chemical burns.
- Thermal burns and harmful temperature.

The selection of appropriate hand protection shall be based on an evaluation of the performance characteristics of the hand protection relative to the task(s) to be performed, conditions present, duration of use, and the hazards and potential hazards identified.

Selection of the appropriate hand protection shall be specified by the (ISSoW Permit to Work System) Risk assessment and supported by an SDS if appropriate.

Appropriate hand protection shall be worn, by all employees, contractors and visitors whenever on site, including offshore facilities, Ras Laffan and other industrial cities.

The selection of hand protection shall, be supported by a job risk assessment and SDS where appropriate. Table 1 details general guidelines which shall be adhered to for hand protection. Specific technical QatarEnergy-IS Specifications for Hand Gloves are detailed in

Appendix A.

TABLE 1 GENERAL GUIDELINES FOR HAND PROTECTION

Hazards	Glove Type	Staff	Work Activities
Minor - Motion	Cut level 3 (close fitting e.g., Granberg Norway or Equivalent (NOT polka dot)	All Employees, Contractors	Light maintenance Low Hazard (Walking around work area, loading –unloading cargo - baggage, Sweeping (housekeeping).
Impact Resistant	Deep Grip	Riggers	High risk Manual handling activities, maintenance activities, loading/ unloading of cargo, working with lifting gear – scaffolding & high impact work (Hammering)

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

Hazards	Glove Type	Staff	Work Activities
			Note: The Scaffolders may select either Deep Grip or General Riggers type gloves.
Cuts- Lacerations- Puncture	Kevlar –Level 5 Cut Resistant	All	Any work that requires an open blade activity (Cutting, Sawing etc)
Thermal Burns – harmful temperature	Welders Leather Suede gloves with long gauntlet	Welders Fabrications	Welding Operations (electric and naked flame cutting)
Electrical Burns	Electrical Natural Rubber rated above 110V	Electricians	Electrical work review Procedure
Chemical Burns	Synthetic Rubber (SDS)	All exposed to Hazardous Chemicals	All work activities exposed to hazardous chemicals All chemical handling activities Laboratory work Deep cleaning with caustic solutions Tank entry and cleaning.
Bacterial	Disposable Plastic / Latex	Galley Staff	Food preparation activities and duties – serving of food
Cuts / Puncture	Kevlar - Chain – cut resistant		Food preparation with bones/frozen meats and raw provisions Any open blade activities i.e. working with knives or sharp objects
Biological	Disposable Latex	Medical Staff Galley Staff Cleaning Staff	All hygienic, sterile activity performed by medic Preparation of food Cleaning with non-hazardous detergents
Harmful Temp	ERT Gloves	ERT Team	Emergency Response Teams



IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE

DOC NO : IS-HSE-PRC-005

REV. 04

- Handling of chemicals as per SDS:
- Electrical work activities – Rubber gloves shall be worn inspected before use air test to detect any worn spots, holes or tears subject to comprehensive voltage leakage test every 6 months.
- High risk of possible crush injuries (Hammering – handling heavy equipment) Armoured gloves shall be worn.
- Kitchen – catering crew shall wear disposable gloves and shall be disposed after each use.
- Kitchen crew involved in cutting or chopping of food products shall wear chain mail gloves.
- Emergency Response Teams (ERT) shall wear gloves certified to U.S. National Fire Protection Association (NFPA) Standard 1971 or an international equivalent by a marking permanently affixed to the items by the manufacturer.

4.5 QatarEnergy-IS JEWELLERY POLICY

QatarEnergy-IS prohibits the wearing of jewellery within RLIC, and Offshore locations including marine vessels, this includes:

- Rings.
- Bracelets & necklaces.
- Watches with metallic or steel wrist bands.
- Visible body piercing.

4.6 BODY PROTECTION/CLOTHING

All offshore and onshore employees, contractors and visitors, including Halul and marine vessels shall wear flame retardant coveralls (FRC) to NFPA 2112 Standard, and fitted with a label indicating that the clothing is Flame Retardant (FR).

- Employees shall wear orange coveralls with reflective tape fitted.
- Offshore contractors and visitors can wear their own company coloured coveralls providing they are Flame Retardant.
- It is advisable that under garments worn beneath FR clothing be made of 100% natural fibers. The use of synthetic material undergarments diminishes the protection provided by the FR clothing.
- Any jackets or garments worn over coveralls shall be made of FR material.
- Laundry instructions for FR coveralls and FR jackets is as per the Supplier / Manufacturer.
- Flame Retardant coverall (Garments) shall only be modified by an approved FR Clothing supplier.
- Coveralls shall have Long Sleeves - short or rolled up sleeves are prohibited within QatarEnergy-IS facilities. Loose or floppy clothing shall not be worn to avoid entanglement with moving or rotating equipment.
- Trouser legs shall extend past the ankles and shall not be tucked into the boots, this will ensure maximum protection for the wearer.
- Coveralls shall be clean, serviceable and correctly maintained as per manufacturer instructions.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

- Coveralls shall not be worn that are saturated with grease, oil, hydrocarbons nor have large holes. They shall be laundered or replaced as required. Should coveralls become saturated with oil, fuels or chemicals, the individual shall change clothes immediately and wash affected areas thoroughly. Contaminated coveralls shall be laundered before re-use. Disposal may also be considered for heavily contaminated clothing.

Note: Refer to Appendix B, for the QatarEnergy Specification for Body Protection/ Coveralls.

4.7 EYE AND FACE PROTECTION

All QatarEnergy-IS operational facilities shall wear eye protection.

- Standard of prescription or non-prescription safety glasses shall be to ANSI Z87.1 Standard or international equivalent.
- All safety glasses including prescription glasses shall be equipped with approved side shields.
- Safety glasses shall be distinctly marked to facilitate identification of the Standards to which they comply.
- Dark safety glasses shall not be worn indoors or during the hours of darkness.
- Eye and face protection shall fit correctly, be kept clean and in good repair.
- Prescription safety glasses are available to QatarEnergy-IS employees requiring corrective lens on request. Persons whose vision requires the use of corrective lenses and who by nature of their job duties require eye protection shall adhere to QatarEnergy Procedure, IP-SF-002.
- Contact lenses shall not be worn by employees in an environment where there is a potential of injury from intense heat, chemical splashes or high concentrations of particulate.
- Safety goggles shall be worn to protect the eyes against hazards i.e. Chemical splashes, sprays, vapors and dusts as per the product SDS.
- An approved face shield shall be worn with goggles when handling corrosive liquids or liquids exceeding 120°F (49°C).
- Safety goggles with approved impact resistance shall be worn when using compressed air.
- Face shield and safety glasses shall be worn to protect the face from flying objects during grinding operations.
- Only QatarEnergy-IS approved face coverings that do not restrict the use of QatarEnergy-IS PPE shall be worn. The wearing of non-approved face coverings i.e. towels or balaclava are prohibited at all QatarEnergy-IS locations.
- Welders shall wear tinted lenses for welding and cutting operations in accordance with Appendix B.
- Welding shields are required for electrical arc welding operations (refer to Appendix B). The lenses for these shields shall be impact resistant.
- The fire watch and the welder's helper shall wear tinted lenses (shade 3) to prevent a welding flash (refer to Appendix B).

Exception to wearing eye protection shall be:

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

- Working in an office environment, control room or accommodation
- During Helicopter operations – crew changes

Note: Refer to Appendix C, for the QatarEnergy-IS Specification of Safety Glasses.

4.8 HEAD PROTECTION

Head protection (Hard Hat) shall be worn on all QatarEnergy-IS facilities.

- Hard Hats shall meet ANSI Z89.1 E Standard or an international equivalent.
- Metal hard hats are strictly prohibited on QatarEnergy-IS facilities.
- Hard hats shall be worn with the peak forward, and not worn in the reverse position (exception being the welder's helmet).
- Employees shall not modify or paint their hard hat or suspension, unless authorised by the manufacturer, any hard hats found to be defaced shall be replaced.
- Hard hat service life shall follow the manufacture date, which is stamped on the rim of the hard hat. The service life of a Hard Hat is five (5) years from the manufacture date (Appendix C).
- Employees' hairstyles shall not interfere with the correct fitting of the headgear and long hair shall be tied back or confined in a hairnet.
- Where specific PPE such as face shields or welding hoods is required as per the risk assessment these shall be directly attached to the hard hat.
- Emergency Response Teams (ERT) shall be provided head protection that is certified to U.S. National Fire Protection Association (NFPA) Standard 1971, OSHA 1910.156 or an international equivalent by a marking permanently affixed to the device by the manufacturer.

Note: Refer to Appendix D, for the QatarEnergy-IS Specification for Head Protection.

4.9 FOOT PROTECTION

Safety toe boots shall be worn on all QatarEnergy-IS facilities.

- Footwear shall be equipped at minimum with a 3/8" heel.
- Chemical-resistant boots shall be worn when dealing with hazardous chemicals, these boots shall comply with ANSI Class 75 and the product SDS.
- Chemical boots shall meet the requirements by either having the required safety toe or wearing a chemical protective boot over the safety shoe.
- Footwear with exposed metal on the soles is strictly prohibited.
- Open toe footwear is prohibited to be worn at all QatarEnergy-IS operational facilities.
- Emergency Response Team engaged in emergency response fire suppression activities shall wear safety footwear that complies with U.S. National Fire Protection Association (NFPA) Standard 1971, OSHA 1910.156 or International equivalent by a marking permanently affixed to the device by the manufacturer.

Exception: to wearing safety footwear shall be:

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

- a. Working in an office environment, control room or inside accommodation.
- b. During Helicopter operations – crew changes.

Note: Refer to Appendix E, for the QatarEnergy Specification for Footwear.

4.10 HEARING PROTECTION

Single hearing protection shall be worn at all QatarEnergy-IS facilities where noise is recorded above 85dB or greater and warning signs are displayed.

- Double hearing protection shall be worn, when noise level is 100db or greater.
- Refer to IS-HSE-PRC-008, Hearing Protection Procedure.

Exception: to wearing hearing protection shall be:

- a. When noise levels are recorded below 85dB.
- b. Working in an office environment, control room or inside accommodation.

Note: Refer to Appendix D, for the QatarEnergy Specification for Ear Muff Hearing Protection.

4.11 SPECIALIST PPE

Personal Control Descent Device

The personal escape control descent device (DONUT) offers the means of escape from an offshore structure (PS-1, Remote Wellhead jackets).

Personnel working on offshore structures that have a limited means of escape to the sea, due to the non-availability of boat landings or escape ropes shall be issued with a personal control descent device (DONUT).

Personal issued with a personal control descent device shall be provided with a familiarisation in the deployment and use of the equipment by the facility HSE Adviser (Appendix I).

Personal Control Descent Devices shall be maintained and inspection as per the manufacturer instructions.

Abrasive Grit Blasting

Contractor(s) undertaking abrasive grit-blasting at any QatarEnergy-IS facility shall supply QatarEnergy-IS with a documented method statement and risk assessment that shall identifying the hazards, and controls to reduce the hazard to ALARP.

The required minimum PPE for abrasive grit blasting activities to be worn at all QatarEnergy-IS facilities shall be:

- Air fed blasters hood with attached apron.
- Heavy quality leather gloves designed to protect from abrasive grit.
- Leather boots that conform to American National Standard Z41.1.-1967 or equivalent.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

4.12 MACHINE GUARDING

One or more methods of machine guarding shall be provided to protect the operator and other employees in the machine area from hazards such as those created by point of operation, nip points, rotating parts, flying chips and sparks.

Example of guarding methods are, barrier guards, two hand tripping devices and electric safety devices.

QatarEnergy-IS shall, as far as reasonably practicable, ensure guards are affixed to machinery / plant moving parts or secured elsewhere if for any reason attachment to the machine is not possible.

The guard shall be such that it does not offer an incident hazard in itself.

These include but are not restricted to:

- Fixed plant and equipment where the guarding safeguard are part of the design.
- Hand tools, pedestal grinders and drills with rotating parts.
- Rented mobile plant machinery and equipment.

No machinery guarding designed for the protection of contact or impact with moving parts is to be removed except under ISSoW conditions for work to be performed on the equipment.

Any work / task that require the guarding to be removed with the machinery operating (e.g. dynamic balancing of motors), will be risk assessed and the task participant made aware of the potential entanglement hazards and the mitigation for those hazards.

4.13 GREEN HARD HAT POLICY

All new personnel (QatarEnergy-IS Employees, Contractors and Visitors), shall wear designated colour coded hard hats or hard hat covers as per the following criteria:

Green Hard Hats or Hard Hat Covers:

- All new start personnel with offshore experience but who are new to the location (QatarEnergy-IS, Contractors, Vendors), for a period of 28 offshore working days (One rotation).

Yellow Hard Hats or Hard Hat Covers:

- All onshore based personnel (QatarEnergy-IS, Contractor, Vendor), on day trips or short visits this shall include marine vessels.
- All personnel who are offshore industry newcomers or short-term visitors to the location.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

	
Green Hard Hat Covers	Yellow Hard Hat Covers

QatarEnergy-IS employees visiting offshore facilities (day visitors / new starts) shall be issued with the relevant colour coded hard hat covers by the site Safety Officer.

Contract personnel shall be issued with the relevant colour coded safety hard hats by their employing company prior to their offshore mobilization.

It shall be the responsibility of **ALL** experienced personnel at the facility, to observe and assist any personnel wearing green and/or yellow hard hats or covers (Visitors / New Starts), during their visit or probationary period. Assisting them with daily tasks, advising on QatarEnergy-IS Procedures, systems and safe working practices.

QatarEnergy-IS facility Safety officers / QatarEnergy-IS Representatives (Marine Vessel / Halul), shall ensure that there is a limited number of green and yellow hard hat covers available at the facility, should a person arrive without one.

All QatarEnergy employees and contractors who have been issued a Green Hard Hat/Cover must undergo an evaluation conducted by their direct supervisors, utilizing 'Appendix – I,' upon completion of 28 offshore working days. This evaluation will determine whether they meet the minimum competency level required for transitioning to a white hard hat.

4.14 FALL PROTECTION

Refer to Fall protection Procedure IS-HSE-PRC-048.

4.15 RESPIRATORY PROTECTION

Refer to Respiratory Protection Procedure (IS-HSE-PRC-013) and Hydrogen Sulphide Contingency Safety Procedure (IS-HSE PRC-023).

4.16 PROGRAM MONITORING

Day to day operations compliance monitoring shall be conducted by QatarEnergy-IS Department / Facilities Supervisors and Safety Officers using the available resources:

- Behavioral Based Safety Program – SOC reporting system.
- **Hand Safety Audits (iAuditor)**

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

- **Minimum Inspection Criteria:**
 1. **Glove Condition:** Inspect for tears, punctures, and wear.
 2. **Glove Fit:** Ensure proper fit for user to maintain dexterity.
 3. **Appropriate Glove Selection:** Verify that gloves are suitable for the specific task and hazard.
 4. **Proper Usage:** Check if gloves are being used correctly during operations.
- **PPE Inspection Audit (iAuditor)**
 - **Minimum Inspection Criteria:**
 1. **PPE Condition:** Check for any signs of damage or degradation.
 2. **Correct PPE Usage:** Ensure that PPE is appropriate for the task and used correctly.
 3. **Proper Fit:** Confirm that PPE fits the user adequately.
 4. **Storage:** Verify that PPE is stored properly when not in use

4.17 PPE ON PS-1-Q MAIN DECK

Personnel working on PS-1Q under ISSoW Permit to Work system (IS-FOP-PRC-100) which shall expose personnel to potential hazards / injury shall wear the correct PPE as documented on the WCC.

The Correct PPE shall be:

- Head protection (hard hat)
- Eye protection (safety glasses)
- Hearing protection (ear plugs / muffs)
- Foot protection (safety shoes / boots)
- Hand protection (gloves).
- Any other PPE documented on the WCC.

Personnel transiting (Not working), between PS-1Q offices, accommodation and accommodation barge (if available), shall wear head protection (hard hat), and foot protection (safety boots), as a minimum.

4.18 DOCUMENTATION AND RECORDKEEPING

Training records for employees shall be kept by QatarEnergy-IS as per record retention requirements.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

5.0 REFERENCES TO OTHER DOCUMENTS

Document Title	Document Number	Internal/External Document	Document Referencing
QatarEnergy Life Safety Rules	QP-SAF-COP-021	Internal Document	Upward
QatarEnergy Standard for the Selection and Procurement of PPE	QP-OHH-STD-036	Internal Document	Upward
Hazard Communication Procedure	IS-HSE-PRC-006	Internal Document	Sideward
Respiratory Protection Procedure	IS-HSE-PRC-013	Internal Document	Sideward
Hydrogen Sulphide safety procedure	IS-HSE-PRC- 023	Internal Document	Sideward
Fall Protection Procedure	IS-HSE-PRC-048	Internal Document	Sideward
Standard on Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting	NFPA 1971	External	N/A
Industrial Head Protection	ANSI Z89.1	External	N/A
Permit to Work Governance Procedure	VO-OPS-PRC-069	Internal Document	Upward
Worksite Safety Inspection Procedure	IS-HSE-PRC-003	Internal Document	Sideward

6.0 DEFINITIONS

Term	Definition
Approved PPE	PPE that has been certified as meeting specified design criteria published by a recognized consensus Standards organization, such as the American National Standards Institute (ANSI), the National Fire Protection Association (NFPA), the National Institute for Occupational Safety and Health (NIOSH), or an international equivalent.
Personal Protective Equipment (PPE)	Any protective device(s) worn or used by an employee to prevent exposure of a body part or system to a physical or chemical hazard. Examples include safety glasses, face shields, gloves, chemical protective clothing, safety shoes, fall protection

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

APPENDIX

APPENDIX A - HAND PROTECTION

QATARENERGY HAND PROTECTION SPECIFICATIONS :

Item No.	Description	Unit	Sap Code (For QatarEnergy Office Use Only)
B1	GLOVES: 10 OZ COTTON PVC DOTTED GLOVES (AS PER APPROVED SAMPLE).	20014188	PAIR
B2	GENERAL PURPOSE LEATHER WORK GLOVES: BACK OF HAND & CUFF OF GOOD QUALITY COTTON FABRIC. COTTON LINING, PALM OF HAND, FINGERS & THUMB OF CHROME LEATHER. CHROME LEATHER BAND STITCHED ACROSS THE BACK OF HAND. ELASTIC TIGHTENING BAND. RUBBERIZED CUFF. LENGTH: 10.5" As Per EN 388	20014190	PAIR
B3	GAUNTLET SAFETY GLOVES: CHROME LEATHER, THICK LINING, As Per BS-1651 or equivalence, INSIDE LENGTH: 14" (350MM).	20014192	PAIR
B4	CHEMICAL & ACID GLOVES: MANUFACTURED TO BS 1651 or equivalence, HIGH RESISTANCE TO CHEMICALS, OIL, GREASES & ACIDS. PROVIDES DEXTERITY & COMFORT. SIZE 8.	20014196*	PAIR
B5	CHEMICAL & ACID GLOVES: MANUFACTURED TO BS 1651 or equivalence, HIGH RESISTANCE TO CHEMICALS, OIL, GREASES & ACIDS. PROVIDES DEXTERITY & COMFORT. SIZE 9.	20014197	PAIR
B6	CHEMICAL & ACID GLOVES: MANUFACTURED TO BS 1651 or equivalence, HIGH RESISTANCE TO CHEMICALS, OIL, GREASES & ACIDS. PROVIDES DEXTERITY & COMFORT. SIZE 9.5.	20014198	PAIR

(Taken from: QP-OHH-STD-036 QatarEnergy Standard for the Selection and Procurement of PPE)

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

APPENDIX B - BODY PROTECTION / COVERALLS

QatarEnergy SAFETY COVERALLS SPECIFICATIONS:

1) MATERIAL:

- a. Flame Retardant Work Coverall
- b. Brand: Flash Armor
- c. Article No.: 0105FT36
- d. Fabric Grade: Dupont Nomex III-A
- e. Composition: Nomex / Kevlar / inherently static resistant fibers with 93 / 5 / 2 blend
- f. Fabric Weight: 4.5 Oz.

2) POCKETS:

- a. Two top slanted around 45° inward (\ /) chest pockets with heavy duty brass zipper closures which are covered by small flappers of the same fabric.
- b. Two hip pockets with metal press studs.
- c. One pocket on the right-hand shoulder to fit for a portable radio (8.5x12 cm).
- d. Pen pocket (2 slots) on left sleeve.
- e. Gas detector loop above the left chest pocket.
- f. Two in one tool pocket (19x11cm) on side of right leg.
- g. Two rear pockets – right pocket with flap cover and concealed snap button and left pocket concealed snap button lock without flap cover.

3) STITCHING:

- Fully double stitched & all stress points are bar tacked.
- Permanent sewn crease line.
- Stitched with Nomex thread.

4) FASTENERS & CLOSURES:

- a. Two-way heavy-duty metallic zipper (YKK Brand), snap button & storm flap closure.
- b. Zipper will extend from 1" below top of Collar to Crotch.
- c. A Front Fly closure, a minimum of 1¼" wide, shall cover front and back of Zipper.
- d. 3 Covered snap closures on front of Garment, two at Neckline and one at Waistline.
- e. Brass press studs for hip side pockets and cuffs on the sleeves.
- f. All metal parts are fully concealed.

5) SEAMS:

Seams and joints shall be sewn with serge stitching at Sleeve, Armhole, Shoulder, side & Leg seams, back rise, Crotch, Yoke and Waist seams. Single rows of stitching shall be limited to hems at Wrists and Ankle openings. Enforced (Bar tacking) at all stress points.

6) SLEEVES / CUFFS:

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

- a. Full sleeves with adjustable cuffs with concealed snap button.
- b. Sleeve types: Long

7) COLLAR:

Snap button neck closure with hanging hook on collar. Lapel type collar shall be a one-piece top stitched, double thickness, unlined fitted, turned down, having a 3" finished width (+ / - 1/2").

8) WAIST BAND:

Concealed elastic waistband to be fitted on the back of coverall. Action back allowing body movement.

9) LEGS:

Shall be made of two-piece cloth, leg bottoms shall be 18" to 22" in circumference.

10) COLOR:

Orange color with Color fastness 4-5 and easy care.

11) LABEL:

Each coverall shall have a laundry proof label stitched to the inside back below the neckband. This label shall have:

- a. Name and Trade Mark of the manufacturer
- b. Model of Coverall if available
- c. Garment size (length and chest size)
- d. Sleeve length (short or long)
- e. Care instructions (washing & laundering).

12) WORKMANSHIP:

All coveralls are to be made of high workmanship. All coveralls are to be inspected during manufacturing and at final trimming and packing. All coveralls are to be manufactured using a two-piece method. Jackets and Pants of coveralls are joined together using knitted elastic waist band.

13) STANDARDS:

- Garment is certified to EN 11612:2015
 - A1 – Limited Flame Spread
 - B1 – Convective Heat
 - C1 – Radiant Heat
- Thermal protective performance: NFPA-2112
- Arc thermal protection (ATPV): CLASS 2
- Vertical Flammability: ASTM D 6413-99
- Air permeability: ASTM D 737

14) REFLECTIVE STRIPS:

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

1" Reflective tape (EN 471) on front and back of shoulder, on both the arms and legs.

15) QatarEnergy LOGO:

One computerized embroidered QatarEnergy Logo directly on the right chest pocket.

16) QatarEnergy MOTTO LOGO:

One computerized embroidered "Committed to Excellence" directly on the left chest pocket.

17) SIZES OF COVERALLS:

- Seven (7) different sizes: XS, S, M, L, XL, XXL & XXXL

(Taken from: QP-OHH-STD-036 QatarEnergy-IS Standard for the Selection and Procurement of PPE)

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

APPENDIX C - SAFETY GLASSES / EYE PROTECTION

C-1. QatarEnergy SPECIFICATIONS FOR STANDARD SAFETY GLASSES

Item No.	Description	Unit	Sap Code (For QatarEnergy Office Use Only)
A1	SAFETY SPECTACLES: GREY LENS, SCRATCH RESISTANCE, HARD COATED LENS WITH MOULDED SIDE SHIELDS. TO ABSORB >99% UV RAYS. MEET ANSI Z87.1-2010 OR EQUIVALENT. FRAME COLOR: BLACK/BROWN.	20015994	PC
A2	SAFETY SPECTACLES: CLEAR LENS, SCRATCH RESISTANCE, HARD COATED LENS WITH MOULDED SIDE SHIELDS. TO ABSORB >99% UV RAYS. MEET ANSI Z87.1-2010 OR EQUIVALENT. FRAME COLOR: BLACK/BROWN.	20015995	PC
A3	SAFETY GOGGLES: FOR CHEMICAL, DUST & IMPACT PROTECTION SOFT PVC FRAME, PVC LENS, INDIRECT VENTS ON TOP & BOTTOM. TRANSPARENT. APPROVED TO ANZI Z87.1-2010 OR EQUIVALENT.	20014244	PC

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

C-2. QatarEnergy SPECIFICATIONS FOR PRESCRIPTION SAFETY GLASSES

Item No.	Description	Unit	Sap Code (For QatarEnergy Office Use Only)
1	PLASTIC FRAME WITH PLASTIC POLYCARBONATE SINGLE VISION LENS (TINTED).	PAIR	20021680
2	PLASTIC FRAME WITH PLASTIC POLYCARBONATE BIFOCAL LENS	PAIR	20021681
3	SINGLE VISION PLASTIC POLYCARBONATE LENS ONLY (WITHOUT FRAME)	PAIR	20021682
4	BIFOCAL VISION PLASTIC POLYCARBONATE LENS ONLY (WITHOUT FRAME)	PAIR	20021683
5	PLASTIC FRAME ONLY (WITHOUT LENS).	PAIR	20021684

Note 1: Frame colors Black or Light Brown

Note 2: Eye sizes to cover range 46 to 60

Note 3: Frame shall have side shields (Clear, Fixed)

Note 4: Lenses shall be with Anti scratch coating.

(Taken from: QP-OHH-STD-036 QatarEnergy Standard for the Selection and Procurement of PPE)

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

C-3. SPECIFICATIONS FOR TINTED LENSES

Operation	Shade #
Shielded metal-arc welding - 1/16, 3/32, 1/8, 5/32-inch electrodes	10
Gas-shielded arc welding (non-ferrous) - 1/16, 3/32, 1/8, 5/32-inch electrodes	11
Gas-shielded arc welding (ferrous) - 1/16, 3/32, 1/8, 5/32-inch electrodes	12
Shielded metal-arc welding - 3/16, 7/32, 1/4-inch electrodes	12
Shielded metal-arc welding - 5/16, 3/8-inch electrodes	14
Atomic hydrogen welding	10-14
Carbon arc welding	14
Soldering	2
Torch brazing	3 or 4
Light cutting, up to 1 inch	3 or 4
Medium cutting, 1-6 inches	4 or 5
Heavy cutting, 6+ inches	5 or 6
Gas welding (light) up to 1/8 inch	4 or 5
Gas welding (medium) 1/8-1/2 inch	5 or 6
Gas welding (heavy) 1/2 + inch	6 or 8

NOTE:

During gas welding or cutting where the torch produces a high yellow light, it is desirable to use a filter or lens that absorbs the yellow or sodium line in the visible light of the operation.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

APPENDIX D - HEAD PROTECTION**D-1. QATARENERGY HEAD PROTECTIVE EQUIPMENT SPECIFICATIONS:**

Item No.	Description	Sap Code (For QatarEnergy-IS Office Use Only)
1	SAFETY HELMET Helmet made of: High Density Polyethylene (HDPE) High Dielectric Strength Shell: One-piece injection Weight: Approximately 0.35 Kg Helmet Type: Cap Helmet shall have: Adjustable Harness, Suspension & Perforated Soft Absorbent Sweat Forehead Band, removable safety chin strap (for working at heights) Vented Cap and Point Ratchet Suspension Top Impact Color: White, Green (Safety Officers) Comply to International Standards: ANSI Z89.1.2014 or Equivalent. Class C (printed on the inside of the helmet) Helmet must include the date of manufacture and the manufacturer's name Helmet must be accompanied by the manufacturer's Guidelines for care and service Size: Standard / Medium Slots for attaching Ear Muffs QatarEnergy Logo shall be printed on front (Tri color) and "Qatar Petroleum" printed in Arabic & English under the logo. Shelf Life: 5 years Warranty Period: 1 year	20014207
2	EAR DEFENDER MUFFS Clip – on Version (for mounting on Safety Helmet above) Lateral Pivot on Headband Soft ear cushions High performance attenuation (NRR / SNR: 24 to 28 db) Standard: ANSI S3.19-1974 or EN 352-3:2003 or Equivalent	20014682

(Taken from: QP-OHH-STD-036 QatarEnergy Standard for the Selection and Procurement of PPE)

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

D-2. HARD HAT SERVICE AND CARE REQUIREMENTS

1.HARD HAT SERVICE LIFE GUIDELINES

- a. Hard hat service life shall follow the manufacturer's projected date, which is stamped on the rim of the hard hat. The service life of a Hard Hat is five (5) years from the manufacturer's date.
- b. Inspection of safety hard hat:
 - User shall inspect their hard hat daily, before starting any work activities. Checking for cracks, craze pattern and brittleness. If any of these conditions exist, then the user shall replace the hard hat.
 - Safety hard hats shall be replaced straight away, if they have been subjected to an impact, penetration or has deep gouges
 - Hard hats shall be replaced every 5 years, as from the date of manufacture stamped on the hard hat
 - When cleaning the hard hat use mild soap and water or a cleaner-disinfectant liquid (as approved by HSE). Do not clean hard hat with hydrocarbon-based cleaners.

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

APPENDIX E - FOOT PROTECTION

E-1 QatarEnergy Safety Ankle Boots Specifications:

- a. Color: Black.
- b. Upper Material: Chrome Leather. Water resistant.
- c. Sole: PVC or Nitrile rubber. Anti-static and flexible with Steel or composite material, i.e. TPU plate mid sole anti puncture.
- d. Padding: Fully padded socks & foam padded collar.
- e. Stitched Soles (Stitches shall not be exposed to ground. If any, shall be in Sole Grooves) or Bonded (Using DVP Process).
- f. Toe Cap: 200 Joule Steel Epoxy coated, or composite material TPU.
- g. Boot Width: Medium and Wide
- h. Lace up Type.
- i. Boots shall be stamped for EN 345, ANSI-MI/75 C75, ANSI Z41.1-1991, or ASTM F-2412-05/2413-05.
- j. Meets Safety Standards against Impact, Compression and Penetration.
- k. Boots shall be resistant to Slips (comply with ASTM F695-01), Oils, Fats, Acids, Petrol, Alkalis and Heat (up to 300 Deg. C).
- l. Size: **For Men:** 6 to 12 ½ " on increments of ½" (UK shoe size). **For Women:** 3 to 8 " on increments of ½" (UK shoe size).
- m. Warranty: 1 Year.
- n. SAP Codes (for QatarEnergy office use only): For Men 20021341 to 20021354 and for Women 20021411 to 20021431.
- o. Should be light weight, not exceeding 1 kg, comfortable and of good quality.

E-2 QatarEnergy Rigger Boots Specifications:

1. **COLOR:** Dark
2. **UPPER MATERIAL:** Soft Chrome Leather, Water resistant
3. **SOLE:** Nitrile rubber, Anti-static, with puncture resistant steel or composite thermoplastic
4. polyurethane (TPU) plate midsole (1100N)
5. **SOLE STITCHING:** Stitches shall not be exposed to ground. If any, shall be
6. in sole grooves or bonded (using DVP process)
7. **TOP CAP:** 200 Joule Steel or composite thermoplastic polyurethane (TPU) Epoxy coated
8. **BOOT WIDTH:** Wide (minimum)
9. **RIGGER BOOT TYPE:** Pull up with leather pull-on loops (side or front)
10. **INTERNATIONAL STANDARD:**
 - a. Boots shall be stamped for EN 345 S3, BS1870, or ANSI-M1/75 C75
 - b. Meets Safety Standard against Impact, Compression and Penetration
11. **BOOTS RESISTANT:** Boots sole shall be resistant to Slips, Oil, Fats, Acids, Petrol,
12. Alkalis and Heat (up to 300° C)
13. **SIZE:** USA sizes (36 to 48) or equivalence in UK/EU sizes
14. **WEIGHT:** Shall be maximum 1.2 kg/pair
15. **WARRANTY:** 1 year

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

(Taken from: QP-OHH-STD-036 QatarEnergy Standard for the Selection and Procurement of PPE)

APPENDIX F: WINTER JACKET SPECIFICATION

QatarEnergy SPECIFICATIONS FOR WINTER JACKET:

1. **MATERIAL:** NOMEX DELTA C.
2. **FEATURES:** Anti-static, Inherently Fire-Resistant material with detachable Hood. Comfortable to wear.
3. **INTERNATIONAL STADARD:** BS EN ISO 9002:1994.
4. **UPPER / OUTER SHELLS:** 220 GSM, NOMEX DELTA C.
5. **FILLING:** 150 GSM (Middle layer: Wind Breaker Padding/Felt, 100% Aramid Permanent Heat & Retardant Material – Not Polyester Lining).
6. **COLLAR:** Full neck, non-lapel without any filter materials with zipper all the way to top and a detachable hood (hood to be rolled back in collar and closed with a zipper).
7. **REFLECTIVE STRIPES:** Reflective strips at Back and at the End of Sleeves (2.25 cm width). Brand: 3M.
8. **ZIPPER:** Heavy Duty YKK, Brass.
9. **POCKETS:** - Two (2) front pockets on left and right Chest.
Two (2) lower pockets at both sides of the waist.
One inside pocket on the left side.
The left front pocket shall have the facility to house two (2) pens.
10. **QatarEnergy LOGO:** Shall be embroidered to the left breast pocket.
11. **QatarEnergy MOTTO: “Committed to Excellence”** shall be embroidered to the right breast pocket.
12. **COLOR:** Orange.
13. **SIZE:** S; M; L; XL; XXL and XXXL.
14. **GENERAL:** Bidder to confirm that provided material is NOMEX DELTA C manufactured by DuPont with official documentary evidence proving source of fabric is Nomex Delta C.
15. **INSPECTION:** QatarEnergy shall appoint its own representative or Third-Party Inspection Agency to visit manufacturer’s facilities to inspect quality and source of materials for compliance for the successful Contractor.
16. **INFORMATION TO BE PROVIDED BY MANUFACTURER:**
The manufacturer shall provide:
 - a. Commercial washing, laundering & care (methods and instructions)
 - b. Manufacturing process including dye process / method
 - c. Fiber identification
 - d. Fiber composition
 - e. Color fastness to washing
 - f. Thread per unit length
 - g. Weight per unit area
 - h. Tearing strength
 - i. Mercerization if used
 - j. Sanforization if used
 - k. Yarn size
 - l. Yarn twist
 - m. Air permeability

**IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT
SELECTION & USE****DOC NO : IS-HSE-PRC-005****REV. 04**

- n. Breathability
- o. Safe ironing temperature
- p. Flame resistance characteristics
- q. Wind protection
- r. Oil & water repellant
- s. Allergen & irritation
- t. Brand name and Jacket model.
- u. Country of origin.

(Taken from: QP-OHH-STD-036 QatarEnergy Standard for the Selection and Procurement of PPE)

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005	REV. 04
---	---	----------------

APPENDIX G - GREEN HAT EVALUATION QUESTIONNAIRE

Green Hat Evaluation Questionnaire			
Name:			
Position:			
Company:			
Assessment Questionnaire	Competent		Comments
	YES	NO	
What are the minimum PPE requirements at the workplace?			
When and where do you use double hearing protection?			
What is the correct action and response to take in the event of a GPA?			
Where are the designated muster stations, alternative muster stations and what is your lifeboat number?			
Explain how the T-card system operates			
Where are the nearest telephone facilities and what is the emergency contact number?			
How and when do you use the MAC switch alarms?			
Explain the different alarm sounds			
What H2S hazards are present at your site			
Explain the purpose of the permit to work system			
What is your understanding of our Stop Work Authority policy?			

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE	
	DOC NO : IS-HSE-PRC-005	REV. 04

Name the 9 Life Saving Rules			
How do you check the 15-minute SCBA set before use?			
What are the personal gas monitor requirements?			
What is the current lifting colour code?			
What does Safety HAT stand for?			
What control measures can be implemented to prevent dropped object?			
Which incidents should be reported?			
What are the requirements relating to worksite barriers and the correct process to follow?			
What does the colour coding of a scaffold tag represent?			
What are the responsibilities placed on you, as an employee, regarding working at heights requirements?			
Where can personal electronic devices be used?			

Direct Supervisor / Safety Officer verification

Are the responses given by the employee of an acceptable standard?	YES	NO
--	-----	----

Entered in Database

Date of Joining	
Date of Assessment	
Supervisor Name / Signature	
Safety Officer Name / Signature	

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

APPENDIX H: PERSONAL CONTROL DESCENT DEVICE (DONUT) FAMILIARIZATION

All QatarEnergy-IS personnel and contractors that are issued with a Personal Control Descent Device (DONUT) shall receive familiarization on how to don the equipment and its operations during a controlled descent.

Familiarization conducted by: Safety Officer

Number of Candidates: 10 Max

Location: Onshore / Offshore

Training material:

- Personal Control Descent Device (DONUT) DVD
- DONUT unit (Demo units will be marked “**DEMO ONLY**” and shall not be used for escape purposes).

Method:

1. Personnel shall watch the Personal Control Descent Device (DONUT) DVD
2. HSE Advisor shall discuss suitable anchor points for the device, this could include a tour of the work station
3. Under the direction of the facility HSE Advisor, personnel shall familiarize themselves by donning and operating the Personal Control Descent Device (DONUT)

Familiarization shall not be conducted from height or over board locations. Personnel shall ensure their feet are firmly located on the ground or deck at all times.

APPENDIX I – REVISION HISTORY LOG

Revision Number: 04

Date: 02/09/2024

Item Revised	Revision Description	Page No.
4.18	Removed the following clause: "The most recent PPE Hazard assessment and PPE matrix is retained on the HSE team site until it is updated." This change has been implemented because this clause is currently not practiced as a standard procedure. Clause in question originated from the OPQL legacy, however, it did not become standard practice after the transition period.	15
5.0	Incorporation of the newly developed IS-HSE-PRC-003 Worksite Safety Inspection Procedure.	16
Appendix H & I	Appendices related to the Hand Safety Inspection Form and PPE Inspection Form have been removed from the procedure, as these inspections will now be managed under IS-HSE-PRC-003 and iAuditor.	27, 30

	IS PROCEDURE FOR PERSONAL PROTECTIVE EQUIPMENT SELECTION & USE DOC NO : IS-HSE-PRC-005 REV. 04
---	---

4.16	Incorporated minimum inspection criteria for Hand Safety Audits and PPE Inspection Audits, detailing specific checks for glove condition, fit, selection, and usage, as well as PPE condition, correct usage, fit, and storage in Section 4.16 Program Monitoring.	14, 15
Remarks :		

APPENDIX J – LIST OF ABBREVIATIONS

Term	Definition
ALARP	As Low As Reasonably Practical
ANSI	American National Standards Institute
ERT	Emergency Response Team
FR	Flame Retardant
ISSoW	Integrated Safe System of Work
NFPA	U.S. National Fire Protection Association
NRR	Noise Reduction Rating
PPE	Personal Protective Equipment
RPE	Respiratory Protective Equipment
SCBA	Self-Contained Breathing Apparatus
SDS	Safety Data Sheet
WCC	Work Control Certificate