



Document Effective Date
25/03/2025

WORK INSTRUCTION FOR TRACKING & CALIBRATION OF MONITORING DEVICES

DOC NO: IS-HSE-WKI-012

Rev: 02

Quality Reviewed By: OMB/4(I)

 Digitally signed by Moklis Miah
Date: 2025.03.20 08:51:16 +03'00'

CUSTODIAN DEPARTMENT	DOCUMENT AUTHOR	DOCUMENT OWNER
HEALTH, SAFETY & ENVR (IDD EL-SHARGI)	 Digitally signed by Mohamad Khairil Azhar Mohd Salim	 Digitally signed by Nasser Abdulla Al Naimi Date: 2025.03.24 12:44:03 +03'00'
	OHE/2(I)	OHE(I)

FINAL APPROVAL	
	Digitally signed by Ibrahim Al-Ahmad Date: 2025.03.25 10:00:17 +03'00'
OH(I)	

	WORK INSTRUCTION FOR TRACKING & CALIBRATION OF MONITORING DEVICES DOC NO: IS-HSE-WKI-012	REV. 02
---	--	---------

TABLE OF CONTENTS

	Page No.
1.0 PURPOSE	3
2.0 SCOPE AND APPLICABILITY.....	3
3.0 WORK INSTRUCTION STEPS	3
3.1 Process Workflow.....	3
3.2 List of HSE Monitors & Equipment	3
3.3 Workflow.....	4
4.0 REFERENCES TO OTHER DOCUMENTS	5
APPENDIX.....	5
APPENDIX A - REVISION HISTORY LOG.....	5
APPENDIX B - LIST OF ABBREVIATIONS	5

	WORK INSTRUCTION FOR TRACKING & CALIBRATION OF MONITORING DEVICES DOC NO: IS-HSE-WKI-012 REV. 02
---	---

1.0 PURPOSE

The purpose of this Work Instruction is to ensure efficient coordination, calibration and control of HSE monitors and equipment distributed at various locations within QatarEnergy-IS facilities and locations.

2.0 SCOPE AND APPLICABILITY

This Work Instruction is applicable all locations within QatarEnergy-IS Asset.

3.0 WORK INSTRUCTION STEPS

3.1 PROCESS WORKFLOW

Stock of the monitors and equipment shall be maintained by Industrial Hygienist or any personal designated by Head, Environment & Regulatory Affairs in HSE Department. Dispatch of equipment to offshore locations will be from IH and communicated and manifested for tracking purposes. Return of equipment will be manifested and communicated to IH prior to dispatch.

Calibration will be coordinated with 3rd party vendors by IH.

Control of the monitors and equipment whilst offshore will be the responsibility of the HSE Advisor at each location or the IS Rep where there is no available HSE Advisor. A record of HSE monitors and equipment at each location will be maintained by IH and reviewed periodically for scheduled or overdue for calibration.

A spare for each item will be maintained in QatarEnergy IS office for equipment in frequent use; Not for one off specialized equipment. If the spare has been shipped and a further item requires repair, service or calibration IH will coordinate between the locations for a temporary back up where operational activities permit.

All field requests for HSE equipment and monitors as detailed above will be via IH. The process workflow is in section 3.3.

3.2 TYPE OF HSE MONITORS & INDUSTRIAL HYGIENE EQUIPMENT

The following is a list of type of HSE monitors and industrial hygiene equipment used within the QatarEnergy-IS facilities and locations.

No	Type of Equipment	Subtype
1	Radiation Survey Meter	• Radiation Dosimeter, • Radiation Survey Meter (Geiger Muller, Probes & etc.) • Radiation dose survey meter.
2	Industrial Hygiene Equipment	• Indoor Air Quality monitors & probes. • Sound Level meter & acoustic calibrator • Chemical Sampling pump & air sampling calibrator




WORK INSTRUCTION FOR TRACKING & CALIBRATION OF MONITORING DEVICES

DOC NO: IS-HSE-WKI-012

REV. 02

No	Type of Equipment	Subtype
		• Portacount – Respiratory Fit testing machine. • Heat Stress thermometer (Heat Index) • Laser Thermometer

3.3 WORKFLOW



	WORK INSTRUCTION FOR TRACKING & CALIBRATION OF MONITORING DEVICES DOC NO: IS-HSE-WKI-012 REV. 02
---	---

4.0 REFERENCES TO OTHER DOCUMENTS

Document Title	Document Number	Internal/External Document	Document Referencing
Procedure for Personal Protective Equipment Selection and use	IS-HSE-PRC-005	Internal	Sideward
Procedure for the use and testing of equipment Containing a low radioactivity sealed source	IS-FOP-PRC-229	Internal	Sideward
Heat Stress Procedure	IS-HSE-PRC-031	Internal	Sideward

APPENDIX

APPENDIX A - REVISION HISTORY LOG

Revision Number: 02

Date: 16/03/2025

Item Revised	Revision Description	Page No.
Section 3.2 & Appendix C	Document revised to address Internal IMS Audit finding OBS-FPAI24-006.	3 & 3
Remarks:		

APPENDIX B - LIST OF ABBREVIATIONS

Abbreviation	Description
QatarEnergy-IS	Idd El-Shargi Asset of QatarEnergy
RLIC	Ras Laffan Industrial City
IH	Industrial Hygienist

	WORK INSTRUCTION FOR TRACKING & CALIBRATION OF MONITORING DEVICES DOC NO: IS-HSE-WKI-012 REV. 02
---	---

APPENDIX C – FORMAT FOR MONITORING OF EQUIPMENT CALIBRATION

*This is the minimum info required to maintain the list.

No	Brand & Model Description	Serial Number	Type of Equipment's	Date Calibrated	Calibration Due	Location	Site Personnel Involved
1	Ludlum NORM Meter	25020682	Radiation Survey-Ludlum	17.02.2025	17.02.2026	Al-Wajba	Offshore Material Coordinator Rig Al-Wajba (ISND)
2	Ludlum NORM Meter	PR402133	Ludlum Probe	17.02.2025	17.02.2026	Al-Wajba	
3	Ludlum NORM Meter	PR402841	Ludlum Probe	17.02.2025	17.02.2026	Al-Wajba	
4	Aeroqual 500 & probe	XXXX	Indoor Air Quality Meter	XXXXXX	XXXXXX	PS-1	
5	Sound Level Meter	XXXX	XXXXXX	XXXXXX	XXXXXX	RLIC Mud Plant	Viju
6	Rados RDS-110	XXXX	Radiation Survey Meter	25.01.2025	25.01.2026	Office	None
7	TSI Portacount	XXXX	Respiratory fit test machine	XXXXXX	XXXXXX	PS-1	