

**Questions, remarks, queries coming from the Train-the-Trainer
for the CIC MARPOL ANNEX VI, during PSC Seminar 65, June 2018**

Question 1 Are bunker delivery notes, with details of fuel oil for combustion purposes, kept available on board for the required period of 3 years?	Response
If the vessel has bunker delivery receipts, which contain the same information as bunker delivery notes, would that be acceptable instead?	YES, this should be considered as acceptable.
When to tick N/A in this question?	For ships < 400 GT, the answer to this question should be N/A, even if they have BDN on board. Furthermore, if the answer to Question 4 is YES, there is a possibility to answer N/A to this question.
When to tick YES in this question?	Question 1 should be limited to the checking of the existence of BDN and if they contain at least the information specified in Appendix V to this Annex. If during the checking of the BDN, all the required information is provided, except the sulphur limit, the answer to the question should be YES. As regards the sulphur limit, Question 2 is dedicated to this subject.
What about ships, that are not bunkering ships, that deliver fuel to other ships (e.g. from one offshore supply vessel to another), are they obligated to give BDN to the other vessel?	YES, they are obligated to give BDN to the other vessel.
In such a case who will be the supplier?	The supplier is stated in BDN.
In cases where the suppliers provide a non-compliant bunker delivery note, should this be considered a deficiency?	YES, this should be considered a deficiency.
In addition, who is responsible?	The ship is responsible and should on receipt of the BDN verify that required information is contained within the BDN.
Which action taken code should be taken? 17 + 99?	It would be situation dependent and up to the professional judgement of the PSCO with reference taken to Guidance on Action taken and Deficiency Codes. Code 99 should only be used when other codes do not apply.
Question 2 Do bunker delivery notes indicate that fuel oils delivered and used on board is not exceeding the maximum allowed sulphur content, as appropriate?	Response
When to tick N/A to this question?	If the answer to Question 4 is YES, there is a possibility to answer N/A to this question.

What happens if the sulphur limits indeed are not compatible?	The PSCO should refer to Guidelines for Port State Control Officers Checking Compliance with MARPOL Annex VI - Follow-up actions.
If there is no correspondence between the BDN and the oil record book (ORB) or if any non-compliance in regard to the filling of the ORB is found (e.g. the bunkering not properly recorded in the ORB), is that related to this particular question?	YES. Use code 01315 (Oil Record Book) instead of 14617.
Does overlap between Question 1 and Question 2 equal possible double deficiency?	NO. Q1 focuses on the requirements for details to be mentioned in the BDN and the requirement for maintaining the BDN available for 3 years. Q2 focuses on the sulphur limits.
Should the sulphur content be recorded in the ORB?	YES, the type and quantity.
Question 3 Do ships which are using separate fuel oils to comply with the maximum sulphur content of 0.1% m/m in fuel oil while operating in SOx emission control areas, have a written procedure showing how fuel oil change-over is to be done for achieving compliance with the above requirements when entering SOx emission control areas?	Response
When to tick N/A to this question?	For ships not using separate fuels (e.g. ships that always use low sulphur) or for ships using alternative arrangements, the answer to this question should be N/A.
Question 4 Are alternative arrangements, (e.g. scrubbers) installed on board according to regulation 4.1 approved by the flag State?	Response
Should it be checked that alternative arrangements are working properly, or is that out of the scope of the question?	YES, this should be inspected similarly with all other equipment normally inspected during a (more detailed) PSC. The question relates to the approval of the alternative arrangements. If approved by the flag State the question should be answered YES. The operation of the alternative arrangements is however out of the scope of the CIC and any deficiency in this regard should be recorded in the report of inspection but not linked to the CIC.
If approved alternative arrangements are installed on board but NOT used during the inspection, should the answer to this question be YES or NO?	The answer should be YES
Regulation 13 is related with Nitrogen Oxides	Any alternative arrangements shall be included

(NOx). Which are the alternative arrangements for NOx?	in the supplement to the IAPP certificate, ref. Appendix 1 of MARPOL, Annex VI.
An equivalent arrangement that is at least as effective in terms of SOx emission reductions as compared to using a fuel oil with a sulphur content limit value of 3.5 % m/m, that means that we might find o/b fuels with a sulphur limit above 3.5%?	There might be found o/b fuels with a sulphur limit above 3.5%. These can only be used with scrubber or alternative arrangements.
Fitted, approved but not used?	See the supplement art. 2.3.2
Reg 14 / 15 also apply to NOx, how to deal with that?	Regulation 14 covers sulphur and Regulation 15 covers VOC.
Question 5 Do ships which are using separate fuel oils to comply with the maximum sulphur content of 0.10% m/m in fuel oil and entering or leaving SOx emission control areas, record detailed information showing that the ship has completed/initiated the change-over in the logbook prescribed by the Administration?	Response
For MS that do not neighbor SECA and for ships occasionally passing SECA, how far back should logbooks be checked when answering this question? In other words how "pragmatic" should the PSCO be when answering this question?	A "pragmatic" approach should be used if the vessel is coming from SECA immediate to non-SECA. If the recording is not OK, a deficiency should be considered. Wrong recordings belonging to past history of the vessel should not result in a deficiency. This will rely on a PSCO Professional Judgment
If the answer to Question 1 is NO , then what to do here?	This will rely on a PSCO Professional Judgment
Guidance: In EU ports all ships must have 0,10 S fuel, and it is normal to have a fuel change-over procedure, but if the ship is equipped with a closed loop scrubber, the ship does not need to have a fuel change-over procedure.	The answer should be N/A
Ships that never enter ECA area 1 month/6 months. How to check this? (Ships that never enter ECA area)	The answer should be N/A It can be checked e.g. through the logbook
Question 6 Do ships which have rechargeable systems containing ozone-depleting substances (refer to the supplement to the IAPP Certificate, item 2.1), have the ozone-depleting substances record book maintained?	Response
Should the ship have implemented maintenance procedures?	It is required to be filled in the ozone depleting substances record book.
Question 7 Where an Approved Method in accordance with Annex VI, regulations 13.7.1-13.7.5 (refer to the	Response

supplement to the IAPP Certificate, item 2.2.1) is installed, has such an installation been confirmed by a survey using the verification procedure specified in the Approved Method File, including appropriate notation on the ship's International Air Pollution Prevention Certificate of the presence of the Approved Method?	
When to tick N/A to this question?	Where an Approved Method in accordance with Annex VI, regulations 13.7.1-13.7.5 is not installed
Question 8 For ships equipped with a shipboard incinerator or thermal waste treatment device installed as an alternative arrangement, is the ship's crew responsible for the operation of the equipment familiar with, properly trained in, and capable of implementing the guidance provided in the manufacturer's operating manual?	Response
Why is the focus solely on incinerators installed on and after 1 January 2000? What about incinerators installed before 1 January 2000?	The IAPP supplements provides information for ships with incinerators before 1 January 2000, ref. MARPOL, Annex VI, Reg. 16. According to Regulation 16.6.1 each incinerator subject to this subparagraph shall be approved by the Administration.
How to deal with incinerators installed before 1 January 2000?	The answer should be N/A
Question 9 Are the master and crew familiar with essential shipboard procedures in the approved VOC Management Plan relating to the prevention of air pollution from ships?	Response
When to tick N/A to this question?	If not required, the answer should be N/A
Question 10 Does the ship keep on board a Ship Energy Efficiency Management Plan (SEEMP)?	Response
Question 11 Was the ship detained as result of the CIC?	Response