

- Dig trench approximately 2 feet deep
- Remove existing old pipe
- Pour new concrete slab
- Inspect materials for cracks