501:AS trace2 = write_LBC | write_CMD | write_COR | write_CRC | write_FLR | write_FAR | write_CTL | write_STAT | write_FDRI | write_RES_E | write_MASK;