flybywire A380X

BEFORE STA	RT
SECURITY INSPECTION	COMPLETE
CKPT PREP	COMPLETE
OXYGEN	SET
GEAR PINGS & COVERS	REMOVE
FUEL QTY	LBS +/ LBS
T.O DATA	SET
ALTIMETER	_ INHG/HPA SET
PARK BRK	SET
SIGNS	ON/AUTO
WINDOWS/DOORS	
BEACON	ON

AFTER ST	ART
ANTI ICE	
F/CTL	
RUDDER TRIM	NEUTRAL
PITCH TRIM	CHECK
GROUND EQUIPMENT	CLEAR

BEFORE TAKEOFF
FLIGHT INSTRUMENTSCHECK
TAKEOFF BRIEFINGCONFIRM
V1/VR/V2/FKEX TEMP CHECK
SIGNSON
SPLRSARM
FLAPS
AUTOBRAKERTO
T.O CONFIG NORMAL
CABIN CREW READY
PACK 1+2 AS REQUIRED
EXTERIOR LIGHTSSET

AFTER TAKEOFF/CLIMB	
LDG GEARUP	
FLAPS0	
PACK 1+2ON	
APU MASTEROFF	
LAND LIGHTOFF	
ALTIMETER STANDARD SET	

APPROACH	
CABIN CREW	ADVISE
LANDING DATA	SET
AUTOBRAKE/BTV	. AS REQUIRED
LANDING BRIEFING	CONFIRM
ECAM STS	NORMAL
ALTIMETER	QNH/HPA SET
LAND LIGHT	ON
MINIMA	SET
SEAT BELTS	ON

LANDIN	IG
A/THR MODE	
SIGNS	
LDG GEAR	DOWN
FLAPS	LDG
SPLRS	ARM

AFTER LANDING
EXTERIOR LIGHTSSET
SPLRSDISARM
FLAPS0
APUSTART

PARKING
PARK BRKON
EXT LT AS REQUIRED
APU BLEEDON
ALL ENGsOFF
FUEL PMPsOFF
SEAT BELTSOFF

SECURING THE AIRCRAFT	
ADIRSOFF	
OXYGENOFF	
APU BLEEDOFF	
EMER EXIT LTOFF	
SIGNSOFF	
APUOFF	
ALL 3 LAPTOPSOFF	
ALL 4 BATTERIESOFF	