MEM 103 Unit 3, Lesson 7

Lesson 7 Self-Check Questions

- 1. Dump box and heated metal pattern are used in
- a. Investment castingb. Shell-mould casting
- c. Centrifugal casting d. Die casting.
- 2. The typical thickness of the shell in shell moulding process is approximately
- a. 5 mm
- b. 10 mm
- c. 15 mm
- d. 20 mm.
- 3. For manufacturing precision investment castings the sand generally used is
- a. Zircon sand
- b. Silica sand
- c. Chromite sand
- d. Olivine sand
- 4. For making vanes or blades of a turbine, the recommended method of casting is
- a. Shell moulding
- b. Permanent moluld casting
- c. Precision investment casting
- d. Die casting
- 5. Permanent mould casting is also known as
- a. Corthias casting

c. Pressure die casting

b. Gravity die casting

- d. Slush casting.
- 6. An expendable mould casting process that employs single-use pattern is
- a. Investment casting
- b. Plaster mould casting
- c. Ceramic mould casting
- d. Die casting
- 7. Compared to many casting processes, the dimensional accuracy and surface finish of the parts produced by sand casting process is
- a. poor
- c. very good
- b. good
- d. excellent
- 8. In investment casting, the pattern is made of
- a. wax
- c. plaster of paris
- b. plastics
- d. ceramics
- 9. Precision casting is another name used for
- a. Shell-mould casting

b. Centrifugal casting

c. Investment casting

- d. Permanent mould casting.
- 10. Refractory slurry is used in

MEM 103 Unit 3, Lesson 7

- Shell-mould casting Investment casting a.
- C.

- b. Centrifugal castingd. Die casting.

Possible answers to self check questions

1. b 2. b

3. а 4. С

5. b 6. а

7. а 8. a

9. С 10. c