

Phase Voltage 220

Current 15

Machine Pump A1

Inspection Report

Inspector John

Status Active

Voltage Analysis

Voltage 440

Load 20

Machine Health Report

Machine Motor X1

Status Good