

SCRAP REASON AND SCRAP COST Scrap Reas.. Null 50K 150K 100K




Number of Records

MEASURE VALUES AND MEASURE NAME

Scrap Cost







WORK CENTER AND NUMBER OF **RECORDS**

