



CONVERT 3D MODEL INTO 2D DRAWING USING SOLIDWORKS TASK SCHEDULER


Create the template using the Drawing Template format (*.drwdot).




Open
SolidWorks
Task Scheduler
and create a
new task.




3D Model Files







After adding the template location and the 3D model folder location or one by one file location, set the start time and click the Finish button.



After the task is created, it runs at the scheduled time and completes successfully. The duration may be longer if the parts are large.




The given output is shown in the folder.



Final output

- When the drawing file 'whatever' is added to the template, it appears like this.
- This step is also used to convert drawings into PDF and other formats.



Note: This automation is used to schedule drawing creation so it can be done, without being physically present on the shop floor.