
Area change
1e−4
0.0
−0.2
−0.4
−0.6
−0.8
−1.0
Work − stored − dissipated [N mm]
Canonical: current area
Test: reference area
0.0
0.2
0.4
0.6
0.8
1.0
Closed-cycle path coordinate
Basis change at constant area
1e−4
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
Work − stored − dissipated [N mm]
Canonical: current area
Test: reference area
0.0
0.2
0.4
0.6
0.8
1.0
Closed-cycle path coordinate