

```
from deladect.detection import DelaminationDetector

# creates a interface object for delamination
# detection
# the specimen s is already defined in Section 3.1
interface = s.add_interface(name="i0", lower_ply=
    ply0, upper_ply=ply90)

# detector object
detector = DelaminationDetector(s, interface)

edge_params = {"window_edge": (1, 60),
    "seed_ratio": 0.01}

diffuse_params = {"window_diffuse": (30, 30),
    "diffuse_dx": 20.0,
    "diffuse_dy": 20.0}

# runs the detection of both edge and diffuse
# delaminations
result = detector.detect_both_delaminations(
    cracks=cracks,
    edge_params=edge_params,
    diffuse_params=diffuse_params,
)
```