


c7d28f72c6

lidar tier · 5 rooms · 49.65 m² [46.38, 52.91] · 81.2 s

every value carries a nominal 90% interval · * means the sensor never saw it



Rooms

Room	Area m²	Ceiling m	Walls	Openings
R1	4.38 (4.09-4.67)	3.09	13	2
R2	36.96 (34.53-39.39)	3.09	41	4
R3	3.02 (2.82-3.22)	3.09	5	2
R4	2.74 (2.56-2.92)	3.09	4	2
R5	2.54 (2.38-2.71)	3.09	6	2

Damage and scope

no damage regions found

class would be shape-derived; naming a defect needs appearance

What to be careful of (2)

[warning] mirrors and glass are NOT detected. Two geometric tests were built and neither separates a reflection from ordinary geometry; 12.9% of points sit outside the floor envelope here, which is normal for ceilings and occluded floor. Geometry near any mirror in this capture is wrong and unflagged. The capture protocol asks the operator to approach mirrors at an angle

[info] rooms are split at doorway-width necks and under-split rather than over-split; a merged pair still reports a correct combined floor area, an invented room does not