

North Harbor Pier Coating Manual, revision 5

Section 1 - Decision scope

Evaluate North Pier zones N1 through N4. South Harbor records are distractors.

Use inspected surface area as the weighting basis for coating-loss measurements.

Section 3 - Quantitative criterion

Area-weighted mean loss = $\text{sum}(\text{area} \times \text{loss}) / \text{sum}(\text{area})$.

The quantitative criterion passes at or below 0.35 mm.

Use the latest signed amendment for any invalidated measurement row.

Section 4 - Visual criterion

Five or more critical red-marker defects require repair regardless of mean loss.

Use the inspector's image-key classifications when counting critical defects.

The overall decision passes only when both quantitative and visual criteria pass.

Section 6 - Limits of inference

This inspection does not estimate remaining coating service life.

A contractor marketing claim is not a measured durability result.