/*

Experiment No.: 03

Statement: Make a light intensity meter that represent light intensity on 5 LEDs, such that all LEDs would glow for maximum light, no LED would glow for dark condition, and likewise for in between light intensities.

Date of Exp. : xx/xx/xxxx

Author : Vedanti Pote (A-11)

Code Snippet

```
int ldrPin=A0;
int led[]=\{2,3,4,5,6\};
int loopLed =5;
void setup() {
  Serial.begin(9600);
  for(int i=0;i<= loopLed;i++) {</pre>
    pinMode(led[i],OUTPUT);
    digitalWrite(led[i],LOW);
void loop(){
  int sensorValue=analogRead(ldrPin);
  int threshold=500;
  if(sensorValue>threshold){
    for(int i=0;i<loopLed;i++){</pre>
      digitalWrite(led[i],HIGH);
      }
    }
  else{
       for(int i=0;i<loopLed;i++) {</pre>
        digitalWrite(led[i],LOW);
```

```
}
delay(500);
}
```



