



HSX Roofing Field Report

Prepared by HSX Roofing Inc.

Report Date: 2026-04-10

Project Information

JOB NAME 570 Alden Road	CUSTOMER / PROPERTY MANAGER Milestone Property Management Limited
BUILDING NAME Markham Gate Investments Limited Partnership	JOB ADDRESS 570 Alden Road
BILLING ADDRESS 1600 Steeles Avenue West	CONTACT PERSON Mr. Andrew
PHONE (905) 738-1838	EMAIL —
SUPERVISOR Mr. Andrew	PO NUMBER —
WO NUMBER —	ROOF SYSTEM TYPE —
SERVICE TYPE —	

Leak Source

Skylight

Site Conditions / Findings

The staff working at the desks below the skylight were experiencing excessive heat and strong sun glare. We implemented measures to help reduce these issues and improve their comfort.

Work Performed

Following the same approach, we proceeded with the removal of the skylight dome and installed a premium-grade plywood cover with a white finish to improve both aesthetics and light control. The skylight dome was then properly reinstalled, as illustrated in the attached

photos.

Materials Used

- Premium white plywood
- High-performance caulking
- Corrosion-resistant screws

Notes / Recommendations

—

Before Photos



IMG_0734.jpeg

Progress Photos




IMG_0735.jpeg



IMG_0736.jpeg

IMG_0737.jpeg

After Photos



IMG_0740.jpeg

IMG_0739.jpeg



IMG_0738.jpeg

Signature

SIGNED BY
Roberto Hamasato

No saved signature

APPROVAL ROLE
—