ALGIHAZ HOLDING	LESSON LEARNED FORM	SHEQ

Reference # (LL)	Title	Discipline
AGH-QAM-LL-000058	Title - Lesson LEarned	Precast
Categorization (LL)	**Date**	**Location**
Company	12-10-2026	Zone A

Impact (LL)	☐ Positive ☒ Negative
Description	Transmission cables in waterlogged areas of the Live Mall project must be installed correctly, as improper installation has been identified as a significant issue with adverse impact on the project.
Reference	Test Reference
Why Did It Happen? (Root cause)	Lack of coordination between the civil and electrical teams.
How can we rectify? (Correction)	Better communication is required
How It can Be Avoided in Future? (Corrective action)	Test Corrective Action
Before Photo	
After Photo	

Approval | Status: APPROVED

Prepared by		Approved by	
Designation	QC Manager	**Designation**	Line Engineer
Name	Noura Alharbi	**Name**	Test User 1
Signature		**Signature**	
Date	12-10-2026	**Date**	12-10-2026