


# Robotic Manipulation ELEC60030

**Dr Ad Spiers** 

Task 2 Layouts




### Part 2.a



- Move the three cubes to the empty cube holders
- One cube per cube holder




#### Part 2.b



- Stack all the cubes on one of the empty cube holders
- Rotate the cubes so the red faces face outwards
- Do not touch the gates or bridge




#### Part 2.c



- Pick up the tool (top left)
- Move the tool through the gates
- The tip of the tool needs to be below the lines on the gates
- Points are deducted if you touch the gates
- Drop the tool when the task is finished (you do not need to put it back in the tool holder)



## Part 2.c (Alternative Angle)



 Extra points are awarded for smoothness of movement and speed of completion (in all tasks)

 Note that this is the starting pose of the robot (for all tasks).

