FORM REF-GL · REV. 5

POST-STASIS REFRESHER · REFERENCE SHEET

POST AT EVERY SECTOR OFFICE & MUSTER POINT

DUNEWRIGHT COLONY WORKS

Settlement Site 4 · Construction Division · Safety & Health

WHO'S WHO.

EVERY ROLE, EVERY BADGE ENDORSEMENT AND EVERY TERM IN THE REFRESHER. ONE WORD FOR EACH THING, ON EVERY PAGE.

ROLES

STATION · HAT · CALL SIGN · AUTHORITY

Hats follow station (HS-01). A call sign belongs to the station and stays with it when people rotate (REF-RAD). The chain of command is on REF-ORG. Permits and signers are on REF-PTW.

ROLE	STATION · HAT	CALL SIGN	MAY SIGN OR STOP	BADGE ENDORSEMENT
COMMAND AND SUPERVISION				
Colony Construction Director	The Hub · white	`Hub Actual`	Heads the build. Can stop any work.	None needed
Deputy Directors	The Hub · white	`Hub Ops · Hub Safety · Hub Engineering · Hub Logistics · Hub Medical`	Run their divisions. The Deputy for Safety & Health can stop work site-wide.	None needed
Command desk	The Hub	`Hub Command`	Rebroadcasts every siren and warning on Ch 1. Gives the voice all clear. Can clear an ALL STOP and release a caller from Ch 1.	None needed
Sector Superintendent	One sector · white	`[Sector] Super`	Runs all work in the sector, plus muster and headcount.	None needed
Assistant Superintendent	One sector, day or night · white	`[Sector] Assist Day / Night`	Runs the sector on their shift. Settles permit conflicts the general foremen can't.	None needed
General foreman	One trade, one sector · white	`[Sector] GF [Trade]`	Area general foreman signs PTW-HE. Electrical & Power general foreman signs PTW-EE. Second person when a lock is removed.	Entry supervisor, to sign PTW-CS
Foreman	About 4 crews · white	`[Sector] Foreman [n]`	Signs PTW-HW for their work area, PTW-DG and PTW-SP. Names competent persons. Removes another worker's lock by the formal procedure.	PTW-HW signer, to sign PTW-HW · Entry supervisor, to sign PTW-CS
Crew lead	One crew of about 12 · yellow with white LEAD band	`[Sector] Crew [n]-[n]`	Posts WBGT. Sees every crew member every 30 min. Logs ramp days. Names the fall-rescue method. Confirms the fix before work restarts after a stop.	For each task they do
Crew member	Yellow, or your trade's color	`Crew call sign + number`	Can stop unsafe work.	For each task they do
Buddy	Your assigned partner	`Their own`	Watches you all shift. Can stop work.	None needed
SAFETY, HEALTH AND EMERGENCIES				
Safety & Health officer	About 1 per 75 workers · green	`Safety [Sector] [n]`	Can stop any work. Countersigns PTW-HE. Second person when a lock is removed.	None needed
Industrial Hygiene	Safety & Health · green	`Hygiene [n]`	Samples air, silica, noise and chemicals. Runs the respirator and hearing programs and fit tests. Sets the respirator and spray zone on a spray permit (PTW-SP).	None needed
Atmospheric Office field staff	Safety & Health · green	`Atmos`	Weather, WBGT, wind, watches and warnings on Ch 16.	None needed
Fire & Rescue	Hub HQ and sector teams · red	`Rescue [n]`	Takes command of fire, rescue and hazmat scenes on arrival.	None needed
Medic	FAS or Central Med · red with a white cross	`Medic [n] · [Sector] Aid · Central Med`	Takes over casualties. Can release a caller from Ch 1. Restricts or clears duty.	None needed
Stasis Revival Unit	Revival Med Bay · red with a white cross	`Revival [n]`	Revival clearance and re-clearance. Issues badge, radio and RAMP band.	None needed
Security	Director's staff · black	`Security Desk · Security [n]`	Badges, gates, lost badges. Monitors Ch 2.	None needed
Incident commander	First person on scene, any hat	`Their own`	Runs the scene until relieved, then hands over command out loud.	None needed
Muster warden	A named crew lead for each muster point	`Muster [MP-C1]`	Collects crew headcounts and reports once to the Super on the sector channel.	None needed
First aider	One in every crew, any hat	`Their own`	CPR, Stop the Bleed and first aid until a medic takes over.	First aid / CPR / Stop the Bleed
Fire watch	Trained crew member · own hat plus a red FIRE WATCH vest	`Fire Watch [Sector] [n]`	Stops hot work. Reports "watch complete". No rescue or command authority.	Fire watch
LIFTING AND EQUIPMENT				
Lift Director	Crane & Lift supervisor · white	`Lift Director [Sector]`	Approves LP- plans prepared by Design & Structures. Directs critical lifts. Approves high-sail loads at 20+ mph. Can stop any lift.	Lift Director
Crane operator	Crane & Lift · yellow	`Crane [Sector] [n]`	Can refuse an unsafe lift. Obeys STOP from anyone.	Crane operator, by crane type
Qualified signal person	Crane & Lift · orange	`Signal [Sector] [n]`	The only person who signals a lift. Directs any landing after an ALL STOP.	Qualified signal person
Qualified rigger	Crane & Lift · orange	`Crew call sign`	Rigs loads. Rejects damaged or untagged gear: no tag, no lift. As the lift lead named in the lift briefing, directs routine lifts.	Qualified rigger
Spotter	Trained worker, own hat	`Crew call sign`	Guides moving equipment from the operator's view. Stops the machine.	Spotter
Equipment operator	Heavy Equipment Pool · yellow	`[Machine] [Sector] [n]`	Can refuse an unsafe move. Stops for any STOP.	That machine type
Design & Structures engineer	Engineering · white	`Design [n]`	Prepares lift plans and temporary works designs.	None needed
PERMITS, ENTRY AND ENERGY				
Competent person	Trained worker named by the foreman, any hat	`Their own`	Inspects excavations, scaffolds or fall protection. Spots hazards and can stop work.	Competent person: excavation, scaffold or fall protection
Entry supervisor	Foreman or general foreman · white	`Their own`	Checks tests, lockouts and the rescue plan. Signs and ends PTW-CS.	Entry supervisor
Attendant	Crew member, own hat	`Crew call sign`	Stays outside the whole entry. Counts entrants, orders them out, calls rescue. Never enters.	Attendant
Entrant	Crew member, own hat	`Crew call sign`	Goes inside. Gets out at once on an alarm or the attendant's order.	Entrant
Hot-work worker	Welders, cutters · brown	`Crew call sign`	Does the hot work. Never signs their own PTW-HW.	Hot work
Authorized employee (lockout)	Any trained worker, own hat	`Crew call sign`	Locks out with their own red lock and verifies zero energy.	Lockout-authorized
Group-lockout lead	The authorized employee named in charge	`Crew call sign`	Puts yellow job locks on every isolation point and the keys in the yellow lockbox.	Lockout-authorized
Qualified electrical worker	Electrical & Power · blue	`Crew call sign`	The only workers who test for voltage on electrical systems or work on power-cell terminals. Does PTW-EE work.	Qualified electrical worker
Survey, QA/QC, inspectors	Engineering · grey	`Their own`	Survey locates and marks buried services with Electrical & Power for PTW-DG. Often alone: lone-work rules apply.	None needed
Visitor	Visitors and non-construction staff · purple	`None`	Always escorted. Can still stop unsafe work.	None needed

The RAMP band on any helmet means heat-ramp Days 1–5. Watch that worker and check on them first.

BADGE ENDORSEMENTS

NO BADGE ENTRY, NO TASK

THE RULES

- **No badge entry, no task.** Crew leads and foremen check the badge before they assign work.
- **Pre-stasis qualifications are re-verified by a practical test before use.** Stasis dulls skill and reaction time. An old card counts for nothing until you pass here.
- Module or supplement first, then the endorsement, then the task.
- An expired endorsement is suspended until you refresh it. The badge shows each expiry date. (SITE RULE)
- Retrain early after an incident or near miss in that task, after unsafe work is seen, or for new equipment or methods. (SITE RULE)
- Records are kept by the Director's staff.

YOUR BADGE LISTS

- Completed modules and supplements.
- Endorsements for machines, permits and roles, with expiry dates.
- Respirator fit-test date.
- Heat-ramp status.

Lost badge: tell your crew lead the same shift. The crew lead reports it to the Security Desk. Never lend your badge.

ENDORSEMENT	CLEARS YOU TO	LEARN IT IN	REFRESHER
Crane operator	Operate that crane type.	HS-06 · REF-HS	Certification every 5 years (OSHA 1926.1427). Practical evaluation every year (SITE RULE).
Lift Director	Approve LP- plans and direct critical lifts.	HS-06	Every 3 years (SITE RULE).
Qualified rigger	Rig loads and inspect rigging gear.	HS-06	Every 3 years (SITE RULE).
Qualified signal person	Signal crane lifts.	HS-06 · REF-HS	Every 3 years (SITE RULE).
Spotter	Guide moving equipment.	HS-06 · REF-HS	Every 3 years (SITE RULE).
Competent person: excavation	Inspect excavations and stop work.	HS-06	Every 3 years (SITE RULE).
Competent person: scaffold	Oversee scaffold erection, inspect scaffolds and stop work.	Supplement C (HS-SC)	Every 3 years (SITE RULE).
Competent person: fall protection	Inspect fall protection, check rescue plans and stop work.	HS-04	Every 3 years (SITE RULE).
Entry supervisor	Sign and end PTW-CS.	Supplement A (HS-SA)	Every year (SITE RULE).
Attendant	Attend confined-space entries.	HS-SA	Every year (SITE RULE).
Entrant	Enter confined spaces.	HS-SA	Every year (SITE RULE).
Fire watch	Stand fire watch.	HS-05 · HS-09	Every year, with hands-on extinguisher training (OSHA 1910.157(g)).
Hot work	Weld, cut, braze and do torch work.	HS-05	Every 3 years (SITE RULE).
PTW-HW signer	Sign PTW-HW for your work area.	HS-05	Every 3 years (SITE RULE).
Lockout-authorized	Lock out with your own lock. Lead a group lockout when named.	HS-07	Procedure review every year (OSHA 1910.147(c)(6)).
Powder-actuated tools	Use that tool.	HS-07	Every 3 years (SITE RULE).
Qualified electrical worker	Test for voltage, work on power-cell terminals, do PTW-EE work.	Supplement B (HS-SB)	Retraining at least every 3 years (NFPA 70E).
Scaffold erector	Build, move, alter and take down scaffolds, under the scaffold competent person.	HS-SC	Every 3 years (SITE RULE).
MEWP operator	Operate that boom or scissor lift type, after familiarization on the model.	HS-SC	Every 3 years (SITE RULE).
Forklift / telehandler	Operate that truck type.	HS-06	Evaluation at least every 3 years (OSHA 1910.178(l)).
Equipment / printer operator	Operate that machine type.	HS-06	Every 3 years (SITE RULE).
Shuttle driver (Transport staff)	Drive site shuttles.	HS-06 · HS-SD	Every 3 years (SITE RULE).
First aid / CPR / Stop the Bleed	Be your crew's first aider.	HS-09	Every 2 years (AHA course card practice).
Respirator fit test (date)	Wear that exact respirator model and size.	HS-02	Every year, and whenever your face changes (OSHA 1910.134(f)). Medical evaluation before your first fit test (1910.134(e)).

GLOSSARY

EVERY TERM ON EVERY PAGE · A TO Z
RADIO PROWORDS: REF-RAD

ACRONYMS & UNITS

AED
Automated external defibrillator. Talks you through shocking a stopped heart. At every FAS, shelter, structure cooling station and lift muster.

ALL STOP
"ALL STOP, ALL STOP" on any channel, or 3 short siren blasts. Stop all motion, hot work and machine operation, and hold position.

ANSI · ASME
Old Earth standards bodies: American National Standards Institute; American Society of Mechanical Engineers (crane and sling standards B30).

APF
Assigned protection factor. How much cleaner a respirator keeps your air when it fits and is worn right. APF 10 means one tenth of the outside level.

AR · FR
Arc-rated and flame-resistant clothing. FR resists catching fire. AR is also tested and rated against arc flash.

Ch
Radio channel. Ch 1 is Site Emergency. Full plan on REF-RAD.

CO
Carbon monoxide. Toxic gas with no smell or color, from engines, fires and burning polymers. Entry limit under 35 ppm.

CO_2
Carbon dioxide. Your body senses rising CO_2. It can't sense missing oxygen, so low oxygen gives no warning.

CPR
Cardiopulmonary resuscitation. Chest pushes 100–120 a minute, 2–2.4 in deep.

dBA
Decibels, A-weighted: sound level as your ear hears it. Every 3 dB more is double the sound energy. Hearing protection at 85 dBA (site rule).

DCW
Dunewright Colony Works, the employer.

FAS
Forward Aid Station. One per sector, call sign "[Sector] Aid". All injuries and illness go here.

fc
Foot-candle: the light falling on a surface. About 10.8 lux. Night minimums are on HS-SD.

GF
General foreman.

GFCI
Ground-fault circuit interrupter. Cuts the power when as little as 4–6 milliamps leaks to ground, for example through you.

GHS
Globally Harmonized System for chemical labels: red-diamond pictograms, one signal word (Danger or Warning), hazard statements.

GMAW · FCAW · GTAW · SMAW
Welding processes: MIG, flux core, TIG and stick.

H_2S
Hydrogen sulfide. Toxic gas that smells of rotten eggs, then kills your sense of smell. Entry limit under 10 ppm.

HEPA
High-efficiency particulate air filter, on dust collectors and vacuums.

HS-IR
Incident report form. Filed with your Colonist ID.

ICS
Incident Command System. One commander at a time, jobs given by name, command handed over out loud.

IH
Industrial Hygiene. Samples air, silica, noise and chemicals; runs the respirator and hearing programs. Call sign "Hygiene [n]".

kV
Kilovolt: 1,000 volts.

LEL
Lower explosive limit: the least gas or vapor in air that can ignite. Meters read % of LEL. Entry stops at 10%. No hot work at 1% or above (site rule).

LP-
Critical lift plan number.

MEWP
Mobile elevating work platform: boom lifts and scissor lifts. Supplement C (HS-SC).

MP
Muster point, MP-A1 to MP-H2. Two per sector.

N95
Disposable filtering facepiece. Filters at least 95% of particles. No use against oil mist, gas or low oxygen. APF 10.

NFPA 704
The fire diamond. Blue health, red flammability, yellow instability, white special hazards. 0 is minimal, 4 is severe.

NIOSH
Old Earth US National Institute for Occupational Safety and Health. Sets RELs.

NWS
Old Earth US National Weather Service. Source of the heat index.

O_2
Oxygen. Safe range 19.5–23.5%.

OSHA
Old Earth US Occupational Safety and Health Administration. Sets PELs and most standards on these posters.

OV
Organic vapor: the respirator cartridge for solvent vapors.

P100
Particulate filter that stops 99.97% of particles, oil mist included. Fits half- and full-face respirators.

PAPR
Powered air-purifying respirator. A battery blower pushes filtered air into a hood or mask.

PEL
Permissible exposure limit: OSHA's legal limit, usually an 8-hour TWA.

PPE
Personal protective equipment.

ppm
Parts per million.

psig
Pounds per square inch, gauge.

PTW
Permit to work: PTW-HW hot work, PTW-CS confined space, PTW-HE heat entry, PTW-EE energized electrical, PTW-DG dig permit, PTW-SP spray permit. All on REF-PTW.

QA/QC
Quality assurance and quality control. Grey hats.

REL
Recommended exposure limit: NIOSH's health-based limit, often stricter than the PEL. Usually a TWA over a workday of up to 10 hours.

ROPS
Rollover protective structure: the cage on a machine. It protects you only with your seat belt on.

SDS
Safety data sheet. 16 sections. At the chem store and on the site terminal.

SIMOPS
Simultaneous operations: jobs close enough to endanger each other. Checked before a permit is signed (REF-PTW).

SRL
Self-retracting lifeline. A lifeline on a reel that locks in a fall, like a seat belt.

SRU
Stasis Revival Unit. Runs Revival Med Bay. Red hat with a white cross. Call sign "Revival [n]".

START
Simple Triage and Rapid Treatment. Sorts casualties in about 30 seconds each: green, yellow, red, black.

TB MED 507
Old Earth US Army heat bulletin. Basis of the DCW work/rest table.

TWA
Time-weighted average: your average exposure over a shift.

UV
Ultraviolet light, from the sun and welding arcs. Burns eyes and skin, and weakens slings and helmets.

WBGT
Wet-bulb globe temperature. A heat-stress reading that counts air temperature, humidity, sun and wind. Posted by your crew lead at muster and hourly.

Z87
Mark on safety eyewear that meets ANSI Z87.1.

$\mu g/m^3$
Micrograms per cubic meter. Silica PEL 50, action level 25.

SITE & SAFETY TERMS

Acclimatizing
Days 6–14 of the heat ramp. Full work/rest table. Your crew lead checks you every 15 min at WBGT 85+.

Action level
The exposure where monitoring and medical checks start. Silica: 25 $\mu g/m^3$.

All clear
One 15-second tone, then Hub Command on Ch 1: "All clear, all clear, [area]." Never act on the tone alone.

Anchor
The fixed point your lanyard or SRL clips to. 5,000 lb per worker, or designed by a qualified person with a 2:1 safety factor.

Approach boundary
Shock boundary around exposed live parts (NFPA 70E). Unqualified workers stop at the limited approach boundary and cross only with a qualified worker who briefs them and stays with them. Supplement B (HS-SB).

Arc eye
A UV burn on the surface of the eye from a welding arc. The pain starts hours later.

Arc flash
An explosive burst of heat and light from an electrical fault. Supplement B (HS-SB).

Attendant
Stays outside a confined space for the whole entry, counts entrants, orders them out and calls rescue. Never enters.

Authorized employee
A worker trained to lock out a machine with their own red lock.

Badge endorsement
A badge entry that clears you for a machine, permit or role. No badge entry, no task.

Blind lift
A lift where the operator can't see the load or the signal person. Radio only. Stays stopped if comms drop.

Blowing-dust advisory
Visibility 1 mile or less. No outdoor hot work.

Buddy
Your assigned partner. You watch each other all shift.

Call sign
The radio name of a station. It stays with the station when people rotate (REF-RAD).

Capacitor bank
Holds charge after the power is off. Discharge it and keep it grounded.

Central Med
The hospital at the Hub: serious cases (reds), surgery, ICU.

Check-in
Crew lead to foreman every 30 min on the foreman talkgroup. Missed: immediate call-back, then someone goes in person after 5 min.

Class E
Hard hat tested at 20,000 volts (ANSI Z89.1). Worn by electricians.

Class 2 · Class 3
Hi-vis garment classes (ANSI/ISEA 107). Class 3 has sleeves and the most reflective area. Class 2 by day, Class 3 at night.

Colonist ID
Your ID number. On every sign-off, every HS-IR and your personal lock.

Competent person
A trained worker named by the foreman for excavation, scaffolds or fall protection, able to spot hazards and with authority to stop work. Old Earth meaning (OSHA 1926.32): can identify existing and predictable hazards and is authorized to fix them promptly.

Cooling station
Shade, water and an ice trough on every deck of an active structure. Also the shift weigh station.

Crew channel
Your foreman talkgroup.

Critical lift
75%+ of chart capacity, two or more cranes, personnel, over occupied structures, or an unusual load. Needs an LP- plan.

Deck
A level of a structure. Deck 0 is the ground. Below grade is Deck minus 1, and so on.

D-ring
The steel ring between your shoulder blades on a full-body harness. Your fall-arrest lanyard or SRL clips here.

Dunecrete
Alkaline sand-polymer binder. Burns wet skin. Cutting it makes silica dust.

Engulfment
Being swallowed by flowing sand, liquid or polymer.

Entrant
A worker cleared to go inside a confined space.

Entry supervisor
A foreman or general foreman with the HS-SA endorsement. Signs and ends PTW-CS.

Exclusion zone
An area roped off and kept clear: under overhead work and loads, around a crane's swing, on haul roads.

Fall clearance
The distance needed below your anchor to stop before you hit anything. 18.5 ft with a 6 ft shock-absorbing lanyard.

FerroLattice-7
Printed structural polymer, extruded at about 500°F.

Fire watch
A trained crew member in a red FIRE WATCH vest who watches hot work and stays 60 min after it (NFPA 51B). No rescue or command authority.

First aider
Trained in CPR and Stop the Bleed. One in every crew.

Foreman talkgroup
Radio talkgroup for crew check-ins and routine crew traffic, for example "C-F14".

Free fall
The distance you drop before your fall arrest starts to work. 6 ft max.

Grid · grid post
A numbered block, 1–40, inside a sector. The number is painted on every grid post.

Group lockout
Yellow job locks on every isolation point, keys in a yellow lockbox, and a personal lock from every worker on the box.

Group-lockout lead
The authorized employee named in charge of a group lockout.

Hasp
A clamp that holds several padlocks on one isolation point.

Hatch
An opening into a confined space, tank or hull void.

Heat index
The NWS "feels like" temperature in shade, from air temperature and humidity. Site heat levels use it up to 124°F, and air temperature from 125°F.

Heat levels
Normal, Caution, Extreme caution, Danger, Extreme, Extreme heat entry, Site closed (HS-03).

Heat ramp
Days 1–5 capped at 20/40/60/80/100% of the shift in heat, and half the table's work minutes on Days 1–4 (“No limit” = 30/30). Resets to Day 1 after fever, vomiting or diarrhea, any heat illness, or 7+ days away from heat work.

High-sail load
A wide, flat load that catches wind: wall panels, hull plate, roof sections.

Hot work
Welding, cutting, grinding, brazing or torch work. Needs a PTW-HW outside a welding bay.

The Hub
Site command, Central Med, Fire & Rescue HQ and the Atmospheric Office.

Hub Actual
Call sign of the Colony Construction Director in person. "Actual" means the commander, not the desk.

Hub Command
The site command desk at the Hub.

Hull void
The space between hab walls and decks. Often purged with inert gas.

Incident commander
The first person on scene, until relieved, who hands over command out loud. Fire & Rescue takes fire, rescue and hazmat scenes.

Inert gas
Argon or nitrogen. Pushes oxygen out. One breath can drop you.

Intrinsically safe
Built so it can't make a spark or get hot enough to ignite flammable gas. Required for lights and radios where flammables are possible.

Isocyanates
Chemicals in spray foams, polyurethane coatings and QuickSet C-4X. A leading cause of work-related asthma. They sensitize.

Isolation point
A disconnect, valve or blind where energy is shut off and locked.

Lanyard
The strap between your harness D-ring and the anchor. A shock-absorbing lanyard tears open to soften the stop.

Leading edge
The open edge of a deck or roof that moves as work goes on.

Lift Director
The Crane & Lift supervisor (white hat) who approves lift plans and directs critical lifts.

Lift lead
A qualified rigger (orange hat) named in the lift briefing who directs a routine lift. The Lift Director directs critical lifts.

Lift talkgroup
The radio talkgroup named on each lift plan, for example "Lift C-07". Ch 11 is for coordination only.

Location format
Sector-grid, structure, deck, landmark: "Charlie-14, Tower B, Deck 3, east stair."

Lockout · tagout
Every energy source isolated and held at zero under your own lock. A tag alone is only a warning.

Locks
Red: personal, engraved with your Colonist ID. Yellow: job lock for group lockout. Blue: Electrical & Power isolation. One person, one lock, one key.

Lone work
Working out of sight of others. None at Caution or higher, at height, in confined spaces or near wadis and trenches.

Magnetic field rig
A lifting magnet or field-forming rig. Lower the load, dump the coils, verify the field is at or below the rig's posted safe level with a gauss meter.

Man down
Emergency type for a collapsed or hurt person when no other type fits, including a burn with nothing still burning.

Microsleep
A few seconds of sleep, often with the eyes open. A fatigue warning sign.

Muster warden
A named crew lead at each muster point who collects headcounts and reports once to the Super.

Near miss
An event that could have hurt someone and didn't. Report it on HS-IR.

New waker
Slang for a newly revived worker. Every new waker starts on the heat ramp.

One lay
The length of wire rope in which one strand makes one full turn. Used to count broken wires.

Permit board
The board at every structure where every live permit is posted.

Permit-required confined space
A confined space with a dangerous atmosphere, engulfment, a trapping shape or another serious hazard. On this site every confined space counts as one (site rule) until the entry supervisor signs a written certificate at the hatch that every hazard has been removed (HS-SA).

Power cell
Site battery. Always live. It can't be drained.

Purge tag
A tag on a hatch meaning inert gas has been used inside.

Qualified electrical worker
Electrical & Power worker (blue hat). The only workers who test for voltage or work on power-cell terminals.

Qualified person
Old Earth term (OSHA 1926.32): someone who has proven, by degree, certificate or long experience, that they can solve problems in that subject. Qualified rigger, qualified signal person and qualified electrical worker are badge endorsements here.

QuickSet C-4X
Epoxy-isocyanate fast-cure resin. A sensitizer. A big mixed batch can run away and ignite.

RAMP band
Black-and-yellow chevron band reading "RAMP", with a reflective strip, worn front and back of the helmet on heat-ramp Days 1–5. RAMP isn't an acronym. It's "ramp" in capitals so it reads from a distance.

Revival Med Bay
The SRU's clearance bay: clearance, weigh-in, badge, radio, RAMP band, and re-clearance after illness or injury. Not for injuries.

Rhabdo
Rhabdomyolysis. Muscle breakdown after hard work in heat. Dark urine. It can wreck your kidneys.

Safety-critical role
A role where one slow reaction can kill someone else. Hour limits on HS-SD.

Sector
One of 8 site areas, Alpha to Hotel.

Sensitized
Your body has become allergic to a chemical such as an isocyanate or epoxy. Even a trace can set off asthma or a rash. It's permanent.

Shelter
Sealed, cooled shelter with a two-door airlock, in every grid block. Call sign "Shelter [Sector]-[grid]".

Shift weigh station
The scale at the cooling station. Weigh in and out. Pull off at 2% body weight lost.

Site rule
A DCW rule stricter than, or extra to, the Old Earth standards. Always labeled "(site rule)".

Sleep inertia
Grogginess after waking. Wait 15 minutes after a nap before safety-critical work.

Spotter
A trained worker who guides moving equipment from where the operator can see them.

Spray permit (PTW-SP)
Permit for spraying isocyanates or VeilCoat. Industrial Hygiene sets the respirator and spray zone; the area foreman signs (site rule). One location, one shift. See REF-PTW.

Stop-work authority
Anyone can stop unsafe work, with no penalty. Restart only when the crew lead confirms the fix with the person who stopped it.

Structure printer
Gantry machine that prints structures. Ch 12, call sign "Printer [Sector] n".

Suspension trauma
Blood pooling in the legs while you hang in a harness. Can make a conscious worker pass out in minutes.

Swing radius
The area a crane's turning body and counterweight sweep. Barricaded.

Tagline
A rope used to steer a load from outside its fall zone.

Talkgroup
A radio group for one team: a foreman talkgroup or a lift talkgroup.

Toe board
The board at the foot of a guardrail that stops tools being kicked off. 3.5 in minimum.

Triage colors
Green minor, yellow delayed, red immediate, black expectant (START). Never used for heat levels.

Type C soil
The least stable soil class. All site sand counts as Type C. Max slope 1.5:1 (34°).

VeilCoat
Nano-ceramic heat-shield spray with a flammable solvent.

Wadi
A dry stream channel that floods in minutes. Leave wadis, trenches and low cuts at a flood warning.

Watch · warning
Sandstorm watch: possible within 2 hours. Sandstorm warning: expected within 30 minutes. Land loads, get down, go to shelter.

Work face
The place where your crew is working.

Zero energy
Every energy source isolated, released and tested at zero before any part of you goes into a machine.

STOP-WORK AUTHORITY

Every role on this sheet carries it. **Anyone can stop unsafe work. No penalty, no questions.** Stop it, make it safe, tell your crew lead (your foreman if there's no crew lead; any green hat if it isn't fixed). Work restarts only when the crew lead confirms the fix with the person who stopped it. Every stop is logged.

Adapted from Old Earth standards: OSHA 1926.32 definitions (competent and qualified person), OSHA 1926.1427 crane operator certification, OSHA 1910.178(l) powered industrial truck training, OSHA 1910.134 respiratory protection, OSHA 1910.147 control of hazardous energy, OSHA 1910.157(g) extinguisher training, NFPA 70E, ANSI Z89.1, ANSI/ISEA 107, AHA CPR, FEMA ICS. Refresher intervals marked "(site rule)" are DCW rules.