REMINDING OF INDUSTRAI BOMER AND SPRAY PAINTING

(2) Nouves ledar rood = 4,700

(3) binding tape = 2,000

(4) Sihireres = 1,800

(5) air dry vanish = 3,200

(6) lead out mire = 2,500

(4) bearing 2 pie 3000x 2 = 6,000

58,000

SPRAY PAINTING

(OSE # 6,800

Jule Kernelung July 10/11/23