

## THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

	The second second			nical integrity keje		Reg No: AHD 303 XA		
Contra	ct No	1	(	Focal Point:				
Contra	ct Holder	Peter A	KPOKOJE	Company:	SHUON	Location: Wo J		
S/N				Details of Faults	/Deficiencies			
1	LH	Sule re	er type (	Crack:				
2	RAH	Both Sides of rear hidication light not working						
3	Cample Ro-call bretten of Limit							
4	Poulde hat ma goods offer to Historia logo chant, were Rope Certific							
5		operatur Competency, driver Gance and DEP and Webicle Parties						
6			1					
7								
8								
9								
	Please r	ectify defects	within 10 workir	ng days and call 0807	70239380 for re-inspection	on, otherwise a complete re-		
nspec	tion woul	d be required	with a new pre-	mob request.				
Vame:	Can		hurber		lame:			
varne.		7. ~			. [:			
Sign/D	ate:	SOURCE	M CM	TILLA KAD:	ign/Date:			
				11/120,97				
		IME	SHELL PERNOLI	Technical Integrity	NT COMPANY OF NIGER y Reject Report			
Conti	ract No	1.		Focal Point:		Reg No: ABM AID XA		
	ract Holde	r Peter &	TKPOKOTE	Company:	SCHCON	Location: WOJ		
			1 .0					
S/N			1	Details of Fault	ts/Deficiencies			
1	Bec	on treely	san ton J	Kma				
2	LIF	+ Side	rear Ste	erp lack	Cylinder Us			
3	Posi	tun 01	Switch .	to the her	n should be	Placed at the times		
-	D	200		sument for	the forklest	and Oberation		
4	Lines		The second secon					
	Com	Detano.	a) du		end DeDi	1.		
5 6		petency	and dr	wer Leance	and Depi			
5	Cou		and dr		and Depi			
5 6			and dr	wer Leance	and Depi			
5 6 7	Wa	the the	SWL r	wor License nank on t	he body.			
5 6 7 8	Wa	the the	SWL r	wor License nank on t	he body.	ion, otherwise a complete re-		
5 6 7 8 9	Wra	rectify defect	SWL r	Nor Leonoe Nark on H	he body.	ion, otherwise a complete re-		
5 6 7 8 9	Please ection wo	rectify defect	SWL C	Mor Leonoe Mark on H sing days and call 086 e-mob request.	he body.			
5 6 7 8 9 inspe	Wra	rectify defect	SWL C	wor Leance nank on H ting days and call 080 e-mob request.	070239380 for re-inspect			