


IN I OGWO

MECHANICAL RESOURCES





Enur Udoanka Akpan (Last bus stop)

#102 Emenike str. Mile 1

Diobu Port Harcourt

Tel: 07064196331

Sir,

QUOTATION FOR THE REPAIR OF V671 DETROIT GM ENGINE

Mixing of diesel and engine oil inside the engine

This is to inform you that we have inspected your V6 Detroit Gm Engine and have the pleasure to assure that we can repair to free from present fault.

Our quotation for material and labour is as follow;

1. Spare parts required to be changed

A. Serving of 6 Injector Nozzles each is $\frac{1}{20,000}$ x 6 = $\frac{1}{20,000}$

B. Serving of fuel pump and fuel-line is \$\frac{1}{2}\$ 30,000 \$\rightarrow\$ \$\frac{1}{2}\$ \$\frac{1}{2}\$ \$\frac{1}{2}\$ \$\frac{1}{2}\$\$ \$\frac{1

C. Labour charge for the job is N 50,000

Total = $\frac{1}{2}$ 200,000

I will be grateful if my request is granted, for a mutual and cordial business

. Illepan.

Management

relationship.

6555092713 FideLity Bark Plealth Udoeka