

## VEHICLE MAINTENANCE REQUEST FORM

VEHICLE REGISTRATION NO: FE 303 PHC
VEHICLE MAKE: Cherwolet
S/No. Details of Problem
1 Fuel Pump
2 Fuel strayner **
3) Dropping of fuel tank
Requested By: Signature:
Requesting Department HR/ADMM
HR/Admin Manager Comment Mtce Manager, This is for
Your urgent action of Puls
my 12/11/18
Maintenance Supervisor's Comment
the pump is tanky and need replacement.
The pump is faulty and need replacement.  The fuel Hank is direly, need to be clean
Job/Material Certified, 1 8v (Name Suprature Date Chilliple)
1 1211711



HEAD OFFICE ADDRESS: GTC Trans Amadi, Port Harcourt, Rivers State Tel: 07031100346, 08151251116

Motto: In God we Trust

- \* Dealers of Japanese Ca
- \* such as Toyota
- \* Nissan, Honda
- \* Mazda & Mitsubishi

## QUOTATION

CHEVLE! - CAR

O FUEL PUMP\_ #8,000\_00

2 Full Rimp fuller - #1,500

3 DROPING OF PANK - 45,000 00

to PAL Amount-Hy #14,500 00

Innocent. F. Isomos

Kondly +012,000 for the
repair where on an car
TE303 PHC.

## JONAKIN MECH WORK

Specialist on Petrol & Diesel Engine

## **HEAD OFFICE**

#6 Shell Location Road Rumuola-Port Harcourt Phone: 08064018164

AE303 PHC

Date: 8-11-2018

Freel pump and Full ("Straymer. #18,000 droping of fuel tank panels) as 5000

Total # 23,000.00

10h804