ELECTRICAL MAINTENINE PRINTESS GOGOSOA

(1) 100 mosts led courd of Pie

2) sormals choke led 7 pie

3) 32 Aups Industral Socket weale and fermale 1 pro

(4) Buck head Liffing 3 Pic

(5) 24 Volds nanx Cours I pic builth bold in Side

(6, 20 Valts sand, light 1 pic

(4) Eilkling Fithing round type 2 pic

& work way buck head fifting big type 2 pic

Cl 6 mats led bolb Screw type - 14 pre

10,18 mosts led bolb screw type 2 pic

(1)24 Volts De screen bolb 5 pic

(18) Screw Comip holder ceranic type - 8 pic

(13) pass and ticit Isolf and ruf I pack

(4) Insulation take 5 pi