

REQUISITION FORM

Copy to Workshop/Account			No
Orines	16.50		Date: 24/0192019
Required for Price \$\$	03630	<u> </u>	

Code No.	Description	Qty. Required	Qty. Issued	Rate
1	Diesel engine Coil SAE 40.	(100 litre	100 LAN	V
-	high queity Total			
2 V	Diesel Die L filter (Howo			
	od Filter 14 pie Filter)		4805	
3 V	Diesel Fuel Filter No	612600081334	1	./
	(Fuel Filter 4)	60	APCS	V
4	The main engine baltery (make	(200 ahs 1	Low.	44
c = 2	generator better (make	Proporties)	1.00	- /-/
(5)	Julux	((00 au) 1	1 10-	
6	generator Fan bell	(4pkx900)		VV
(F)	the main engine port side	-		1/2
,	and Star board Stde,	(20 pieces)		200
	Stock pump, For bett NO)			
(%)	the main engine uttraha-			12
	tor Fan Selt for portside	1		
(3)	and Star board side	(10 preces)	1-1.00	100
%	turch cable wire spices	(15 metrefu	The two	1000
10	beach pump one for the	/		
Ld	But seter need to be	-		
1	replace	4		

HOD Signature

Received by Signature

(b) the our fifter for both Port Side and star board side is bad we need replacement star board ensine turbochange is bad we need gasket to fix back

Issued by Signature