

## Message preview









Delete Print Mark More Previous Next

## Re: Port main engine lube oil dilution, and steering gear ma 🖪

Compose

From Frawma Services Limited on 2021-03-16 10:40 Details Plain text

300d morning Sir, Mail

Contacts

Also we need seals for the mounting of the pumps which will cost a total of N24,000. Please note, all the internal deals have been replaced as Please the Fuel injection pumps are ready. However, the fuel injectors need replacement of two spray tips at N75,000 each which is N150,000.

part of the overhauling. Two fuel return line fittings must be replaced at N15,000 each, totaling 30k.

Settings

Looking forward to a prompt response regarding said requests.

Thanks and regards

About

Get Outlook for iOS

Logout

Nie

立

Franchis requestive for 2 pieces of injector nozzles, seals for mouthy injection franchis for the follows: amounting to the all return the filthers: amounting to the all of the filthers.

Emanth do not have these spores in stock and efforts so for to compour.

Prices in mile 3 has not visited results. Kindly approxe the soid amount to enable them conclude with the severity.

Mart Israe ( 15/6/12.

1 of 1