PRINCESS DATA

MAINTENTE OF 12.5 K.V.A Jencerator coullet attenentor Set

(1) Sharling ceir dry Vanish 4 Lis = 10,800

(2) binding tape 1/2 coil = 2,800

3) troiuing rope 1 coil = 3,500

(4) aradier slue 1 = 2,500

6, Fuel 12 Lis, 350 × 12 = 4,200

23,800

Jude Meaucheuree