





Figure 23. NUCLEO-L476RG



October 14th
JLCpcb

Gerber file
Speadsheet.xlsx, contiene el BOM

Dentro de los gerbers:
-estan todas las layers
-Tambien hay un archivo top paste para el que solda

Si una via va de la primera a la tercera capa, en la segunda capa tendra que haber un agujero para que no hayan interferencias

El bom lo puede generar altium como un excel
La descripcion se puede crear sola si seleccionamos bien el componente
Active bom se llama

Click derecho y crossflow pasamos del bom al schematic

Hay archivos pdf con visualizacion 3d, son muy buenos

October 21st
Profe quiere todos los testpoints en la cara de abajo, y ninguno tan cerca de otro
GerBV programa para ver gerber

Choke 120 ohm de 0603

IOVDD directo a 3,3V
AVDD conectado a choke y otro C100nF

SB46,SB52 (I2C on A4 and A5)	OFF	PB9 and PB8 (I2C) are disconnected to A4 and A5 (pin 5 and pin 6) on ARDUINO® connector CN8 and ST morpho connector CN7.
	ON	PB9 and PB8 (I2C) are connected to A4 and A5 (pin 5 and pin 6) on ARDUINO® connector CN8 and ST morpho connector CN7 as I2C signals. Thus SB56 and SB51 must be OFF.

