UrbanRoof

Inspection Form

Complete

Score **85.71%** Flagged items **1** Actions **0** **Customer Name**

Mobile:

Email:

Address:

Property Age (In years):

Property Type: Flat

Floors: 11 **Previous Structural audit done** No

Previous Repair work done No

Inspection Date and Time: 27.09.2022 14:28 IST **Inspected By:** Krushna & Mahesh

UrbanRoof

Flagged items 1 flagged Checklists / Inspection Checklists

Checklist:

WC

External wall

UrbanRoof

Site Details

Impacted Areas/Rooms

Impacted Area 1

Hall, Bedroom, Kitchen, Master Bedroom, Parking Area, Common bathroom

Impacted Area

Negative side Description Hall Skirting level Dampness **Negative side photographs**





Photo 1 Photo 2
Photo 3 Photo 4 Photo 5 Photo 6

Photo 7

Positive side Description Common Bathroom tile hollowness

Positive side photographs

Photo 8 Photo 9 Photo 10 Photo 11

Impacted Area 2

Negative side Description Bedroom Skirting level Dampness

Negative side photographs

Positive side Description Common Bathroom tile hollowness

Positive side photographs

Photo 15 Photo 16 Photo 17 Photo 18 Photo 19

Impacted Area 3

Negative side Description Master bedroom Skirting level Dampness

Negative side photographs

Photo 20 Photo 21
Photo 22 Photo 23 Photo 24 Photo 25

Positive side Description MB Bathroom tile hollowness

Positive side photographs

Photo 26 Photo 27 Photo 28 Photo 29 Photo 30

Impacted Area 4

Negative side Description Kitchen Skirting level Dampness

Negative side photographs

Photo 31 Photo 32

Positive side Description Master bedroom bathroom **Positive side photographs**

Photo 33 Photo 34 Photo 35 Photo 36 Photo 37

Impacted Area 5

Negative side Description Master bedroom wall damness **Negative side photographs**

Photo 38 Photo 39 Photo 40 Photo 41

Positive side Description External wall crack and Duct Issue

Positive side photographs

Photo 42 Photo 43 Photo 44 Photo 45 Photo 46 Photo 47

Photo 48

Impacted Area 6

Negative side Description Parking Area seepage **Negative side photographs**

Photo 49 Photo 50 Photo 51 Photo 52

Positive side Description Common Bathroom tile hollowness and plumbing issue

Positive side photographs

Photo 53 Photo 54 Photo 55 Photo 56 Photo 57

Impacted Area 7

Negative side Description Common Bathroom Ceiling Dampness

Negative side photographs

Photo 58outlet Leakage **Positive side Description** Flat no 203 tile joint open and

Positive side photographs

Photo 59 Photo 60 Photo 61 Photo 62 Photo 63 Photo 64

Checklists 1 flagged, 84.21% **Inspection Checklists** 1 flagged, 84.21%

Checklist: WC

External wall

Condition of leakage at adjacent walls

Condition of leakage below WC

Leakage during: All time

Leakage due to concealed plumbing Yes

Leakage due to damage in Nahani trap/Brickbat coba under tile flooring Yes

Positive Side Inputs For WC 100% **Gaps/Blackish dirt Observed in tile joints** Yes

Gaps around Nahani Trap Joints Yes

Tiles Broken/Loosed anywhere No

Loose Plumbing joints/rust around joints and edges (Flush Tank/shower/angle cock/bibcock, washbasin, etc) Yes

Moderate

Type of tile

Negative Side Inputs For External Wall 75% **Condition of leakage at interior side**

Leakage during: All time **Leakage due to concealed plumbing** Yes **Internal WC/Bath/Balcony leakage observed** Yes **Positive Side Inputs for External Wall** 100% **Existing type of paint and manufacturer** Not sure **Stuctural Condition of RCC Members** 100%

Condition of cracks observed on RCC Column and Beam Moderate

Condition of rust marks observed in RCC Beam and Column N/A

Condition of corrosion/spalling of concrete/exposed

reinforcement observed in column/beams/roof slab ceiling N/A

Expansion joints condition if any N/A

Condition of External wall 100%

Are there any major or minor cracks observed over external surface? Moderate

Are the sealants applied on the window frame joints intact? N/A

Condition of wall mounted AC Frames, antennas fixed on parapet wall observed? holes, drain pipes over the wall. N/A

Are the external plumbing pipes cracked and leaked? If yes its condition. Moderate N/A

Are the openings around the pipes in external wall properly grouted? If not its condition. N/A

Condition of any vegetation growth, dish

Condition of Adhesion of old paint 100%

Chalking and flaking in paint film. Algae fungus and Moss observed on external wall? Moderate Bird droppings condition observed on external wall and Chajja Condition of corrosion on metal rods and MS window grills N/A

Substrate condition of Plaster

Patchwork plaster required? if yes its condition?

Entire replaster required? if yes its condition? N/A

Condition of separation cracks observed at beam-column N/A junction

Condition of leakage observed from overhead water tank

Loose plaster/hollow sond on external surfaces?if observed,

SUMMARY TABLE

Point No	Impacted area (-ve side)	
1	Observed dampness at the skirting level of Hall of Flat No. 103	
2	Observed dampness at the skirting level of the Common Bedroom of Flat No. 103	2.1
3	Observed dampness at the skirting level of Master Bedroom of Flat No. 103	3.1
4	Observed dampness at the skirting level of Kitchen of Flat No. 103	4.1
5	Observed dampness & efflorescence on the wall surface of Master Bedroom of Flat No. 103	5.1
6	Observed leakage at the Parking ceiling below Flat No. 103	6.1
7	Observed mild dampness at the ceiling of Common Bathroom of Flat No. 103	7.1

Appendix

Photo 1 Photo 2


Photo 3 Photo 4



Photo 5 Photo 6

Photo 7 Photo 8


Photo 9 Photo 10



Photo 11 Photo 12

Photo 13 Photo 14

Photo 15 Photo 16

Photo 17 Photo 18





Photo 19 Photo 20

Photo 21 Photo 22





Photo 23 Photo 24



Photo

25 Photo 26

Photo 27 Photo 28

Photo 29 Photo 30

Photo 31 Photo 32





Photo 33 Photo 34









Photo 35 Photo 36





Photo 37 Photo 38

Photo 39 Photo 40





Photo 41 Photo 42



Photo 43 Photo 44

Photo 45 Photo 46

Photo 47 Photo 48

Photo 49 Photo 50

Photo 51 Photo 52





Photo 53 Photo 54





Photo 55 Photo 56




Photo 57 Photo 58

Photo 59 Photo 60

Photo 61 Photo 62




Photo 63 Photo 64