# Informe 01: Módulo "Introduction to Onshape"
## Rabanal Bravo Flavio Francisco

## 1.1. Onshape Hands-On Test Drive

### 1.1.1. Copy Course Documents



## 1.3. Navigating a Document

### 1.3.7. Self-Check

What is the minimum number of tabs that a document must contain?

*Choose the correct answer and select Next Question.*

| A. | 0 |
|----|---|
| **B. 1** **Correct!** | |
| C. | 2 |

Next Question

| 1 | 2 | 3 | 4 | 5 |

---

Tabs cannot be moved out of documents.

*Choose the correct answer and select Next Question.*

| A. | True |
|----|------|
| **B. False** **Correct!** | |

Next Question

| 1 | 2 | 3 | 4 | 5 |

---

To rename a document:

*Choose the correct answer and select Next Question.*

| A. | Click the document name in the Document Toolbar. |
|----|--------------------------------------------------|
| B. | Click Rename document in the Document Menu. |
| C. | Right click a part or assembly and click Rename. |
| **D. A & B** **Correct!** | |

Next Question

| 1 | 2 | 3 | 4 | 5 |

To open the Tab Manager:

*Choose the correct answer and select See Results.*

| A. | Click the Tab Manager icon to the left of the document tabs. |
|---|---|
| B. | Use the keyboard shortcut Ctrl-T on a PC or Command-T on a Mac. |
| C. | Use the keyboard shortcut Alt-T on a PC or Option-T on a Mac |
| D. | A & C |

**Correct!**

See Results

| 1 | 2 | 3 | 4 | 5 |
|---|---|---|---|---|

---

# 100%

## Congratulations! You successfully answered all of the questions correctly!

Retake Self-Check

Continue to Next Section