



Department of Chemical Engineering
Thapar Institute of Engineering &
Technology, Patiala

Course: Material and Energy Balances
UCH301

Course Instructor:
Dr. R. K. Gupta, Professor, Chemical Engineering



DEGREES OF FREEDOM FOR A PROCESS



Analysis of Degrees of Freedom

- Identify What is expected from solving the problem
- determine the number of degrees of freedom so that the additional information that is required may be obtained



Degrees of Freedom

- Identify the equations , and decide which equations are to be used if there are redundant equations
- Solve N independent equations for N variables
- Retain in memory the implicit constraints in a problem (What are these constraints?)



- For a given problem there may be (i) no solution, (ii) there may be number of solutions, and (iii) there may be a unique solution
 - (i) $N_d > 0$; (ii) $N_d < 0$; (iii) $N_d = 0$
- First two situations are not satisfactory and tells you that the **problem is not properly posed**. Third situation tells you that the problem is properly specified




- For a unique solution the necessary condition is that the number of unknown variables is equal to the number of independent equations/relations
- Usually, in a material balance problem the number of independent material balances equals the number of components involved
- If Mass flow rate of a stream is F , & there can be several components in material stream as we have seen while solving material balances, then m_i can be denoted as mass flow rate of component i in that material stream



- The mass/mole flow of a component in a stream may be expressed as m_i/n_i , if w_i and x_i are mass and mol fractions and F and M are total mass and mole flows, then

$$m_i = w_i F \quad \& \quad n_i = x_i M$$



- In a mixture of N components, $N+2$ number of stream variables exists (N-1 compositions, 1 total flow, 1 T, and 1 P)



- These variables are either **N** values of m_i , or n_i , as the case may be, or **N-1** values of x_i , and the stream flow F (or M), and T, P



- Let us say that material stream is of Air, now you know that Air has O_2 and N_2 , i.e. two components.
- I have two ways of specifying the data; One: I provide you the amounts of moles of O_2 entering and moles of N_2 entering, Two: I provide you the Total moles of Air entering and composition of any one component in air.




- N-1 mass fraction values are the only independent relation as the implicit constraint $\sum w_i = 1.0$, fixes the value of the Nth mass fraction.
- So for completely specifying a material stream, the number of variables needed are:

$N_{sp} + 2$ (N_{sp} is used for number of species)



Degree of freedom for a mixer




Degree of Freedom

- $N_d = N_v - N_R$
- N_d = number of degrees of freedom
- N_v = Total number of variables
- N_R = Number of independent relations
- $N_v = N_s(N_{sp} + 2) = 3(N_{sp} + 2) = 3N_{sp} + 6$
- N_R : N_{sp} material balances


$$\text{Thus, } N_d = 3N_{sp} + 6 - N_{sp} = 2N_{sp} + 6$$

- What values must be specified?



Including Energy Stream

DoF for Mixer



$$N_d = N_V - N_R$$

$$N_V = N_s(N_{sp} + 2) + 1 \quad (\text{take note of this change})$$

$$= 3(N_{sp} + 2) + 1 = 3N_{sp} + 7$$

N_R : N_{sp} material balances

1 Energy balance

$$N_R = N_{sp} + 1$$

$$\rightarrow N_d = 3N_{sp} + 7 - (N_{sp} + 1) = 2N_{sp} + 6$$

What values must be specified?

