

For a DC generator, there must be a split-ring commutator.



In an AC generator, there are two slip rings.