
(a)
measured pose
only the true pose
only a perfect render
nothing
OFT
LIBERO-10 set A
LIBERO-10 set B
LIBERO-Object
LIBERO-Goal
LIBERO-Spatial
$\pi_{0.5}$
LIBERO-10 set A
7
2
8
n = 17
13
4
4
n = 22
26
8
n = 35
12
2
6
n = 20
3
1
2
n = 6
7
3
9
5
n = 24
0
20
40
60
80
100
raw camera failures, by first repairing rung (%)
(b)
OFT
$\pi_{0.5}$
median
tolerance, about 1 cm
1.5
37.8
2.0
100
10
1
0.1
calibration error (cm, log)
n:
51/3
14/1
19/9
1/0
measured pose
true pose
perfect render
nothing
first repairing rung