COURSE 2 · SECTION 11 · EXERCISE

Capstone: the valve seat ring story

Section 11 · Capstone dashboard

Start: Section11_Start.pbix (the finished S10 file); save as Engxtech_S11.pbix **Time:** about 45 min **Data:** the course data folder

DESIGN QUESTION

Can one report page tell the P300 valve seat ring story from drawing review to field ppm, and let a reviewer drill into any drawing set?

Extra practice. This exercise is extra practice: a longer task than the video's short "Your turn" questions, which are answered in the video itself. Do it after the video, in a copy of your file.

Every visual is built in an earlier section and copied onto one page. The full page spec, layout and acceptance checklist are in S11_Capstone_Brief.pdf. Build it along with the video, or on your own from the brief.

Your tasks

1. Build the 'Seat ring story' page from the brief: three slicers (Parts[PartID], SeatRingRevs[SeatRingRev], BuildMonths[BuildMonth]) and six visuals, with Edit interactions as in the brief.
2. Build the 'Drawing detail' drill-through page (drill field Drawings[PartRev]) with the category Pareto, and the 'ppm counts' tooltip page on the ppm chart.
3. Add two bookmarks, Whole portfolio and Seat ring focus, and a button for each.
4. Set the Part slicer to P300 and read visual 1. Drill through from the P300-B bar and read the numbers in the check table.
5. Write the one-line caption for the ppm chart. It must not say that rev C fixed the problem.

Check your answer

Check	Expected
P300-B review findings	**9**
P300 review findings, all revs	**15**
Drill-through P300-B: drawing / days late / rounds	**DRW-1008 / 19 d / 3**
Drill-through P300-B: major findings / Tolerance	**4 / 6 of 9**
STK-01 rev C: WC / RSS (mm)	**0.006..0.094 (fail) / 0.0298..0.0702 (pass)**
P300 seating load SF, rev B / rev C	**1.53 / 1.78**
GRD-02 Cpk (P300)	**0.787**
ECR-3200 cycle / approval stage	**123 d / 57 d**
Rev B ppm (95 % CI)	**2892 ppm (81/28007); 95 % CI 2297-3595 ppm**
Rev C ppm (95 % CI)	**1710 ppm (4/2339); 95 % CI 466-4379 ppm**

Hint. If drill-through is greyed out, the source visual does not carry the drill-through field: visual 1 must use Drawings[PartRev] on its axis. If a slicer changes a visual it should not, check Format > Edit interactions.

Stuck? The worked solution with the full DAX and M is in Solutions/S11_Solution.pdf.