

RESIDENTIAL FIRE DRILL / EVACUATION RECORD

Site Address: 950 Cedar St

DDSO / Provider Agency: Northstar DDSO

Date: 02/09/2026

Time Evacuation Started: 5:02 AM

Part of Day: Evening

Total time to evacuate to ground: 2 min 52 sec

Total time for all to reach safe area: 5 min

Centrally Monitored Fire Alarm Station: No

Time Monitoring Station Notified of Drill: 7:09 PM

Time Monitoring Station Reactivated: 12:20 AM

Time Monitoring Station Received Alarm: 5:03 AM

Weather Conditions: Snow

Method of Alarm Activation ☐ Pull Station ☒ Smoke Detector ☒ Other

Evacuation Type ☒ Full Evacuation to Outside ☐ Other

Type of Evacuation ☒ Announced ☐ Unannounced ☐ Supervised

Location of Simulated Fire: Bedroom 2

Blocked Exits by Simulated Fire: Front door

Location: Whole house

RESIDENTS & EVACUATION DETAIL

Name	Away?	To Evacuate	At Safe Area	Details
L. Romano	N	2:05	2:29	Assisted
P. Costa	N	3:54	2:21	Used main exit
J. Rivera	N	1:04	5:59	Assisted
T. Nguyen	N	2:55	4:39	Used main exit

Description of evacuation: All residents evacuated calmly via the main exit.

Problems noted / actions: Exit light was dim; bulb replaced.

Did Evacuation proceed per plan: Yes

Were all exits/routes clear: Yes

Did alarms/strobes function: Yes

Was drill observed: No

Did evacuation time meet requirement ☐ Yes ☒ No