
Both FC ports are down for the server below. u0bptwisdbs03 S.Tag: 2J3VMW3 Make & Model: Dell & PowerEdge R750



Both FC ports are up, but FC Slot 4 is currently connected with 16Gbps. It needs to be upgraded to 32Gbps for the server below.

u0bptwisdbn03 S.Tag: 4J3VMW3 Make & Model: Dell & PowerEdge R750

